





report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI
Colour	White
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-14

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-26
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #5	2023-08-24 13:23
MOT test number	771918634774
Result	✓ Passed
Next expiry date	2024-08-26
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #4	2022-08-26 14:58
MOT test number	479369906083
Result	✓ Passed
Advice Play in steering rack inner joint(s) bothsides	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2022-08-25 13:08

MOT test number 215781272793

Result X Failed

MAJOR Central Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Play in steering rack inner joint(s) bothsides

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #2 2021-08-27 14:26

MOT test number 280427097531

Result \rightarrow Passed

Advice Offside Rear Nail in tyre

MOT #1 2021-07-19 14:02

MOT test number 563718647470

Result

Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

CarCheck.co.uk page 4/11



DT18YWX
report date: 2024-03-28

Tax & MOT check





Tax statusValid until 1 SeptemberDays left126MOT expiry date26 August 2024Full MOT historySee MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1


Date

Type Type

Damage 2

Date

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-07-31
Last registration	2023-08-24
Complete history	See info



Registration #1	2018-07-31	20 mi
Registration #2	2021-07-19	29.662 mi
Registration #3	2021-08-27	29.724 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M H4 - C158668LWZ

CarCheck.co.uk page 11/11