





report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 SPORT HDI
Colour	Silver
Year of manufacture	2008
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-14

Pictures 39

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MC	TC	history	
----	----	---------	--

MOT expiry date	2024-05-09
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	16
Total items failed	11

MOT #18	2023-05-10 14:11
MOT test number	510921137500
Result	✓ Passed
Next expiry date	2024-05-09

MOT #	17 2023-05-09 12:4	2
MOT te	st number 82229901141.	3
Result	▼ Faile	k
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail	Offside Front Brake disc in such a condition that it is seriously weakened inner surface (1.1.14 (a) (ii))	
Fail Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))		
Fail (ii))	Nearside Front Brake disc in such a condition that it is seriously weakened inner surface (1.1.14 (a)	

MOT #16	2022-05-05 16:09
MOT test number	751754590151
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

843476350527

Result

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #14

MOT test number

Result

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT test number
987082266374

Result

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



YT08BAO report date: 2024-03-28

MOT #11		2020-02-04 17:10
MOT test	number	773693060117
Result		× Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail S	upplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

MOT #10	2019-02-15 19:05
MOT test number	531583554225
Result	✓ Passed
MOT #9	2018-08-09 13:58
MOT test number	995198387524
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2017-08-11 14:41
MOT test number	584624547278
Result	✓ Passed
Advice Emission to clean to record a reading	

MOT #7	2016-08-19 11:10
MOT test number	716393582431
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #6

Result

YT08BAO

report date: 2024-03-28

2015-08-22 11:01

× Failed

MOT test number 905394984678

Advice Emission to clean to record a reading

MOT #5 2015-08-19 14:44

MOT test number 119479430969

Advice Emission to clean to record a reading

Fail Windscreen wiper does not clear the windscreen effectively Both front (8.2.2)

MOT #4 2014-08-08 12:58

MOT test number 825010024291

Result ✓ Passed

MOT #3 2013-08-19 11:57

MOT test number 877551733242

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2012-08-23 12:57

MOT test number 815306732218

Result

Passed

MOT #1 2011-07-12 11:54

MOT test number 109633391177

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NIE UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-08-08
Last registration	2023-05-10
Complete history	See info



Registration #1	2008-08-08	18 mi
Registration #2	2011-07-12	30.066 mi
Registration #3	2012-08-23	35.677 mi
Registration #4	2013-08-19	38.853 mi
Registration #5	2014-08-08	41.734 mi
Registration #6	2015-08-19	44.283 mi
Registration #7	2015-08-22	44.307 mi
Registration #8	2016-08-19	46.373 mi
Registration #9	2017-08-11	48.568 mi
Registration #10	2018-08-09	50.967 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1653 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/:

Number of axles 2

Engine number DYUK4114590