



report date: 2024-03-28

General information

Make	FIAT
Model	500X T-JET EASY PLUS
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	214 Nm at 2.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-09-22
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-07
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	31
Total items failed	4

MOT #8	2024-04-08 10:40
--------	------------------

MOT test number	870484041217
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-04-07
------------------	------------

Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



MOT #7

2024-03-22 09:31

MOT test number

622315918557

Result

✗ Failed

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Added 2 liters worth of oil

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Coolant level min

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2024-01-27 15:35**MOT test number** 342509791848**Result** ✗ Failed**Advice** Rear Tyre slightly damaged/cracking or perishing Both cracking (5.2.3 (d) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Cracking and cut close to splitting (2.1.3 (g) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt Split (2.1.3 (g) (ii))**Advice** Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Coolant at min**Advice** Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))**MOT #5** 2023-01-25 12:54**MOT test number** 912998760816**Result** ✓ Passed**MOT #4** 2021-10-08 09:52**MOT test number** 158205654703**Result** ✓ Passed**MOT #3** 2021-10-05 14:11**MOT test number** 588378740853**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2021-01-15 10:52**MOT test number** 730034541786**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #1	2020-01-23 09:56
MOT test number	512269916052
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-01-25
Last registration	2024-04-08
Complete history	<a href="#">See info</a>



Registration #1	2017-01-25	19 mi
Registration #2	2020-01-23	29.317 mi
Registration #3	2021-01-15	35.910 mi
Registration #4		
Registration #5	2021-10-05	42.009 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1350 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2148185