





report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Grey
Year of manufacture	2013
Top speed	90 mph
0 - 100 km/h	15.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	31.4 mpg
Consumption combined	28.3 mpg
CO2 emission	266 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1


Date 2021-10-04

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-08
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	22
Total items failed	6

MOT #12	2023-12-05 10:47
MOT test number	700911437978
Result	✓ Passed
Next expiry date	2024-12-08
Advice Offside Rear Lower reflector damaged	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorate ingress of dirt (2.1.3 (g) (i))	ed, but preventing the
Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice Bonnet catch sticking but still secure at time of test	
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor Nearside Front Drag link end ball joint dust cover damaged or deteriorate ingress of dirt (2.1.3 (g) (i))	d, but preventing the
Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	

CarCheck.co.uk page 3/13



MOT test number

MOT test number

WG13KCC

report date: 2024-03-28

925135801378

677603764699

MOT #11 2022-12-05 13:00 297374036032 **MOT** test number ✓ Passed Result **Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) Minor Nearside Front Drag link end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #10	2021-12-09 14:06
MOT test number	316014204274
Result	✓ Passed
MOT #0	2021 11 20 12:27

Result × Failed

Fail Offside Front Headlamp insecure (4.1.1 (c))

Fail Front Registration plate missing (0.1 (a))

MOT #8 2021-09-27 11:46

MOT #7 2021-09-27 11:46

MOT test number 397958906415

Result X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/13



MOT test number

WG13KCC

report date: 2024-03-28

127798311854

MOT #6 2020-09-30 15:25 599999926643 **MOT** test number Result ✓ Passed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #5
 2019-06-13 14:04

 MOT test number
 439137018156

 Result
 ✓ Passed

MOT #4

MOT test number

Result

Minor

Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

 MOT #3
 2017-06-14 14:54

 MOT test number
 512505031237

 Result
 ✓ Passed

MOT #2 2016-06-10 15:29

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement Front bushes. Creates slight knock (2.4.G.2)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2016-06-10 14:41

MOT test number 727784514759

Result ★ Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement Front bushes. Creates slight knock (2.4.G.2)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this LAND ROVER had different number plates.		
See in this check if this LAND ROVER had different number plates.		
See in this check if this LAND ROVER had different number plates.		
See in this check if this LAND ROVER had different number plates.		
See in this check if this LAND ROVER had different number plates.	***************************************	
See in this check if this LAND ROVER had different number plates.	***************************************	
See in this check if this LAND ROVER had different number plates.		
See in this check if this LAND ROVER had different number plates.	***************************************	
See in this check if this LAND ROVER had different number plates.		More info >
ボ 以 に に に に に に に に に に に に に	Plate changes	
	See in this check if this LAND ROVER had different number plates.	
	Number of plates	
Plate since	Current registration	UK NEE
Plate since	Plate since	
Plate since	Current registration	UK UK
	Plate since	
More info >		More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-14
Last registration	2023-12-05
Complete history	See info



Registration #1	2013-06-14	27 mi
Registration #2	2016-06-10	32.608 mi
Registration #3	2016-06-10	32.608 mi
Registration #4	2017-06-14	43.802 mi
Registration #5	2018-05-22	46.414 mi
Registration #6	2019-06-13	55.772 mi
Registration #7	2020-09-30	62.499 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 au
Registration #11		77.777 es
Registration #11 Registration #12		11.07 m
		11,777 ea 11,777 ea 11,777 ea

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



WG13KCC report date: 2024-03-28

		_		
- 11	manci	ODC X	. WA	iaht
וט	mensi	UHSC	\times \vee \vee \subset	ullu

Width	1992 mm
Height	2182 mm
Length	4040 mm
Wheel base	2360 mm
Kerb weight	1759 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Number of axles	2
Engine number	130502003651DT224

CarCheck.co.uk page 13/13