



AV68RVM

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN MATCH TDI
Colour	Silver
Year of manufacture	2019
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	47.9 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-02-04
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #4 2024-01-08 09:19

MOT test number 231012659151

Result ✓ Passed

Next expiry date 2025-01-17

Advice Offside Rear Tyre slightly damaged/cracking or perishing Also worn and feathered on inner edge (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Also worn and feathered on inner edge (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #3 2023-01-10 16:48

MOT test number 126438395399

Result ✓ Passed

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Deep cut in tread (5.2.3 (d) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #2**

2023-01-10 12:33

MOT test number

416582295024

Result**✗ Failed****Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Deep cut in tread (5.2.3 (d) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge 1.7mm (5.2.3 (e))

MOT #1

2022-01-18 14:58

MOT test number

487938688337

Result**✓ Passed****Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-01-14
Last registration	2024-01-08
Complete history	See info



Registration #1	2019-01-14	13 mi
Registration #2	2022-01-18	25.102 mi
Registration #3	2023-01-20	25.277 mi
Registration #4	2023-01-20	25.277 mi
Registration #5	2023-01-20	25.277 mi
Registration #6	2023-01-20	25.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2099 mm
Height	1654 mm
Length	4486 mm
Wheel base	268 mm
Kerb weight	1505 kg
Max. allowed weight	2170 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	DFGAA38639