



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	Red
Year of manufacture	2012
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-04
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-08
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	44
Total items failed	4

MOT #14	2024-01-03 16:06
---------	------------------

MOT test number	310726142152
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-08
------------------	------------

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Minor** Nearside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #13**

2024-01-03 13:16

MOT test number

854685083722

Result**✗ Failed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))

MOT #12

2023-01-09 12:41

MOT test number

323549429304

Result**✓ Passed****MOT #11**

2022-08-03 07:51

MOT test number

263163534924

Result**✓ Passed**

- Advice** Rear Silencer outer skin corroding

MOT #10

2021-08-03 15:42

MOT test number

711423052166

Result**✓ Passed**

**MOT #9** 2021-08-02 16:37**MOT test number** 874305078893**Result** ✗ Failed**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2020-11-24 12:20**MOT test number** 885420409686**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2019-11-12 11:58**MOT test number** 107348824584**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front indicator damaged**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front fog light not working**Advice** Rear exhaust corroded



MOT #6	2019-11-12 09:29
MOT test number	215530771182
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front fog light not working
Advice	Rear exhaust corroded
MAJOR	Nearside Headlamp insecure (4.1.1 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front indicator damaged
MAJOR	Horn not working (7.7 (a) (ii))
MAJOR	Nearside Headlamp aim too high and too far to the left. (4.1.2 (a))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2018-11-09 15:24
MOT test number	649702330765
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4**

2018-11-08 16:37

MOT test number

116620022491

Result**✗ Failed****Advice** Items removed from driver's view prior to test**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (h) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #3**

2017-11-09 12:37

MOT test number

521019167709

Result**✓ Passed****MOT #2**

2017-11-07 12:00

MOT test number

749371712739

Result**✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear rear brake application uneven (3.7.B.2)**Fail** Nearside Front Outer Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1**

2015-10-01 16:31

MOT test number

477299914385

Result**✓ Passed**



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-07-26
Last registration	2024-01-03
Complete history	See info



Registration #1	2012-07-26	22 mi
Registration #2	2015-10-01	13.866 mi
Registration #3	2017-11-07	28.699 mi
Registration #4	2017-11-09	28.709 mi
Registration #5	2018-11-08	37.721 mi
Registration #6	2018-11-09	37.722 mi
Registration #7	2019-11-12	45.637 mi
Registration #8	2019-11-12	45.637 mi
Registration #9	2019-11-12	45.637 mi
Registration #10	2019-11-12	45.637 mi
Registration #11	2019-11-12	45.637 mi
Registration #12	2019-11-12	45.637 mi
Registration #13	2019-11-12	45.637 mi
Registration #14	2019-11-12	45.637 mi
Registration #15	2019-11-12	45.637 mi
Registration #16	2019-11-12	45.637 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0069086