






report date: 2024-03-28

#### General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/14



## Internet history

#### Entry 1

Date 2021-11-21

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



### MOT history

MOT expiry date	2024-12-07
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	21
Total items failed	12

MOT #16	2023-12-07 16:20
MOT test number	184849438577
Result	✓ Passed
Next expiry date	2024-12-07
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))	

CarCheck.co.uk page 3/14



**MOT #15** 2023-12-07 11:32

**MOT test number** 996842369053

**Result** X Failed

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Headlamp insecure (4.1.1 (c))

Fail Offside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

Fail Nearside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Hydraulic brake cylinder leaking hydraulic fluid caliper leaking (1.1.16 (b) (i))

**MOT #14** 2022-12-05 11:00

**MOT test number** 771767603224

**Result** ✓ Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2021-12-08 12:09

**MOT test number** 612874912408

**Result** 
✓ Passed

**MOT #12** 2020-11-04 14:44

**MOT test number** 792899303286

Result \rightarrow Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



MOT #11

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10

2019-10-22 12:51

MOT test number

136236476479

Result

✓ Passed

MOT #9

2019-10-22 12:51

MOT test number

693052102714

Result

Pass with rectification

Nearside Front Direction indicator incorrect colour (4.4.3 (a))

 MOT #8
 2018-10-25 10:15

 MOT test number
 972167344575

 Result
 ✓ Passed

 MOT #7
 2017-10-26 10:59

 MOT test number
 355501629639

 Result
 ✓ Passed

 MOT #6
 2016-10-28 11:40

 MOT test number
 895734337425

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



MOT #5

MOT test number

744269623784

Result

Advice Engine covers and undershields

MOT test number

Result

Advice Engine covers and undershields

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Advice Centre brake light not operating.

MOT #3

MOT test number

569014184266

Result

Notice Daylight offside front not working

CarCheck.co.uk page 6/14



MOT #2 2014-10-10 15:45

**MOT test number** 698943684283

**Result** X Failed

Advice Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Stop lamp not working (1.2.1b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Notice** Daylight offside front not working

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Direction indicators not working (1.4.A.2c)

**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)

MOT #1 2013-08-02 11:50

**MOT test number** 517694613297

Notice NOT CHECKED very rear seat belts cause seats folded down and boot full

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/14





## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	7 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



### Owner history

e when miscory		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
THE PARTY OF THE P		
***************************************		
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK L	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-01
Last registration	2023-12-07
Complete history	See info



Registration #1	2010-09-01	15 mi
Registration #2	2013-08-02	32.621 mi
Registration #3	2014-10-10	45.398 mi
Registration #4	2014-10-11	45.398 mi
Registration #5	2015-10-02	55.721 mi
Registration #6	2015-10-02	55.721 mi
Registration #7	2016-10-28	71.931 mi
Registration #8	2017-10-26	80.108 mi
Registration #9	2018-10-25	88.266 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		0.00 44

More info >

CarCheck.co.uk page 13/14



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 14/14

**Engine number** 

AU21080