



PEUGEOT



KSI2HJC


report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Blue
Year of manufacture	2012
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-21
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	26
Total items failed	22

MOT #16	2024-03-22 09:19
MOT test number	637471561226
Result	✓ Passed
Next expiry date	2025-03-21
Advice	Parking brake lever has little reserve travel
Advice	Nearside front lower fog lamp inoperative
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Oil leak, but not excessive Sump pan (8.4.1 (a) (i))



MOT #15

2024-03-21 18:05

MOT test number

896621698928

Result

✗ Failed

- Pass with rectification

Offside Front Headlamp aim projected beam image is obviously incorrect Bulb not fitted correctly (4.1.2 (c))
- Pass with rectification

Registration plate lamp inoperative in the case of a single lamp or all lamps Offside and nearside (4.7.1 (b) (ii))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Pass with rectification

Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice

Oil leak, but not excessive Sump pan (8.4.1 (a) (i))
- Advice

Nearside front lower fog lamp inoperative
- Pass with rectification

Nearside Front Headlamp aim projected beam image is obviously incorrect Bulb not fitted correctly (4.1.2 (c))
- Pass with rectification

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification

Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice

Brake lever has little reserve travel

**MOT #14** 2024-03-20 14:24**MOT test number** 728341135358**Result** ✗ Failed

- Fail** Nearside Headlamp aim too high light source not located (4.1.2 (a))
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure Tyre repair been done on inner edge and the side wall structure has failed (5.2.3 (d) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive Sump pan corroded and leaking (8.4.1 (a) (i))
- Fail** Windscreen washer not working None of them (3.5 (a))
- Fail** Offside Headlamp aim too low light source not located (4.1.2 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13 2023-03-01 15:05**MOT test number** 666808035833**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12 2023-03-01 14:06**MOT test number** 764868653382**Result** ✗ Failed

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2022-02-08 13:16**MOT test number** 206552530482**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge Both nearside (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2022-02-05 11:50**MOT test number** 274478133708**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge Both nearside (5.2.3 (e))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Windscreen washer not working Both (3.5 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #9** 2021-02-09 08:51**MOT test number** 964840716335**Result** ✓ Passed**MOT #8** 2020-06-17 12:18**MOT test number** 868920503757**Result** ✓ Passed

**MOT #7** 2020-06-17 08:24**MOT test number** 328091669828**Result** ✗ Failed**Advice** Front brake pads getting low**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #6** 2019-06-19 12:01**MOT test number** 729659136336**Result** ✓ Passed**MOT #5** 2018-06-18 14:01**MOT test number** 176576448493**Result** ✓ Passed**Advice** Both front tyres low on edges**Advice** N/s/r tyre low on outer edge**MOT #4** 2017-06-16 08:30**MOT test number** 364096183282**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2016-06-20 16:32**MOT test number** 383196229593**Result** ✓ Passed**MOT #2** 2015-06-24 13:53**MOT test number** 616965375143**Result** ✓ Passed



MOT #1	2015-06-23 14:37
MOT test number	435544975154
Result	✗ Failed
Notice	Front brake discs very corroded and worn.Brake pads also appeare low on friction material
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Rear Exhaust system not adequately supported (7.1.1)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 March 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	21 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-28
Last registration	2024-03-22
Complete history	See info



Registration #1	2012-06-28	20 mi
Registration #2	2015-06-23	31.028 mi
Registration #3	2015-06-24	31.028 mi
Registration #4	2016-06-20	38.407 mi
Registration #5	2017-06-16	45.333 mi
Registration #6	2018-06-18	52.320 mi
Registration #7	2019-06-19	62.008 mi
Registration #8	2020-06-17	66.606 mi
Registration #9	2020-06-17	66.607 mi
Registration #10	2020-06-17	66.607 mi
Registration #11	2020-06-17	66.607 mi
Registration #12	2020-06-17	66.607 mi
Registration #13	2020-06-17	66.607 mi
Registration #14	2020-06-17	66.607 mi
Registration #15	2020-06-17	66.607 mi
Registration #16	2020-06-17	66.607 mi
Registration #17	2020-06-17	66.607 mi
Registration #18	2020-06-17	66.607 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FSX46527121