



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Silver
Year of manufacture	2015
Top speed	117 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-09-07
Pictures	23
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-07-22
Pictures	23
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-09
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	0

MOT #9 2024-02-09 16:27

MOT test number 776048724371

Result ✓ Passed

Next expiry date 2025-02-09

**Minor** All direction indicators flashing more than 120 times a minute (4.4.4 (a))

**Advice** Nearside washers not working

**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8 2024-01-25 09:59

MOT test number 203311083650

Result ✗ Failed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #7 2023-02-01 09:32

MOT test number 838586129923

Result ✓ Passed



MOT #6	2022-02-10 12:56
--------	------------------

MOT test number	603860584491
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2022-02-10 09:03
--------	------------------

MOT test number	591761490495
-----------------	--------------

Result	✗ Failed
--------	----------

**MAJOR** Offside Rear Direction indicator not working (4.4.1 (a) (ii))

MOT #4	2020-11-04 12:54
--------	------------------

MOT test number	137122504687
-----------------	--------------

Result	✓ Passed
--------	----------

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3	2019-12-02 10:41
--------	------------------

MOT test number	563774838447
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2018-11-26 15:08
--------	------------------

MOT test number	357402628333
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #1	2017-11-23 11:11
--------	------------------

MOT test number	925901941710
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
9 February 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	9 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>KV15LZB</b>
Plate since	2015-05-29
Current registration	 <b>KV15LZB</b>
Plate since	2015-05-29

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-01
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2015-03-01	21 mi
Registration #2	2017-11-23	31.438 mi
Registration #3	2018-11-26	44.710 mi
Registration #4	2019-12-02	56.207 mi
Registration #5	2020-11-04	64.848 mi
Registration #6	2020-11-04	64.848 mi
Registration #7	2020-11-04	64.848 mi
Registration #8	2020-11-04	64.848 mi
Registration #9	2020-11-04	64.848 mi
Registration #10	2020-11-04	64.848 mi
Registration #11	2020-11-04	64.848 mi
Registration #12	2020-11-04	64.848 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1911 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 143310091LNQ