





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12




Internet history

Entry 2

Date 2021-09-10

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2021-08-30	
-----------------	--

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-07
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #10	2023-10-07 10:35
MOT test number	469638366650
Result	✓ Passed
Next expiry date	2024-10-07
Advice Front pads wearing low	

MOT #9	2023-10-06 16:28
MOT test number	761979789078
Result	X Failed
Advice Front pads wearing low Fail Front Tyre has ply or cords damaged both (5.2.3 (d) (ii))	

MOT #8		2022-09-28 13:27
MOT test	number	598913404649
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #7 2022-09-28 08:47

MOT test number 257654318618

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #6 2021-09-20 12:33

MOT test number 616890032737

Advice O/s/f tyre low inner

MOT #5 2020-10-08 15:57

MOT test number 774750847706

Result ✓ Passed

MOT #4 2020-10-08 10:16

MOT test number 656199857464

Result X Failed

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #3 2019-05-16 15:37

MOT test number 797328283647

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2019-05-16 11:29

MOT test number 515880511585

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm 215/60R16 (5.2.3 (e))

Pass with rectification Windscreen washer not working Add fluid (3.5 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #1 2018-03-24 09:03

MOT test number 864812719415

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



DN15UXV

report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-04-21
Last registration	2023-10-07
Complete history	See info



Registration #1	2015-04-21	18 mi
Registration #2	2018-03-24	32.600 mi
Registration #3	2019-05-16	48.614 mi
Registration #4	2019-05-16	48.612 mi
Registration #5	2020-10-08	62.429 mi
Registration #6	2020-10-08	62.434 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		D.777 no

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1808 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1361 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	4
Engine number	CAYCAG2518