



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	Silver
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-09-29
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	29
Total items failed	5

MOT #16	2023-09-30 12:39
MOT test number	411286044886
Result	✓ Passed
Next expiry date	2024-09-29
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Shock absorbers has a slightly worn bush Both rear (5.3.2 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases Rear bush (6.1.2 (a))

**MOT #15**

2022-09-07 06:29

MOT test number

103139128343

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view 2x chips (3.2 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive Engine area (8.4.1 (a) (i))

MOT #14

2021-01-28 14:39

MOT test number

109221045901

Result

✓ Passed

- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13

2020-03-18 11:53

MOT test number

594536403373

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2019-03-19 11:21**MOT test number** 144440899504**Result** ✓ Passed**MOT #11** 2018-03-20 08:39**MOT test number** 690880150733**Result** ✓ Passed**MOT #10** 2018-03-20 08:39**MOT test number** 395171376295**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #9** 2017-03-21 13:44**MOT test number** 389613890070**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-03-29 08:34**MOT test number** 916152043335**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-03-09 09:26**MOT test number** 666098265008**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6** 2015-03-09 09:26**MOT test number** 675308065071**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Bonnet retaining device ineffective (8.4.2)**MOT #5** 2014-03-13 09:26**MOT test number** 266372674070**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2013-03-15 09:38**MOT test number** 817944373039**Result** ✓ Passed**MOT #3** 2012-03-19 10:41**MOT test number** 346349572054**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-03-17 15:41**MOT test number** 109016971411**Result** ✓ Passed**Notice** Nearside rear tyre wearing on edges



MOT #1	2011-03-15 09:18
MOT test number	439964471001
Result	✗ Failed
Fail	Offside Front brake disc contaminated by oil (3.5.1h)
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Notice	Nearside rear tyre wearing on edges
Fail	Fuel system component leaking (7.2.3)



Tax & MOT check

✖
Untaxed

Tax expired:
1 November 2022

✔
MOT

Expires:
29 September 2024

Tax status	Expired at 1 November 2022
Days left	546 days too late
MOT expiry date	29 September 2024
Full MOT history	See MOT history



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-13
Last registration	2023-09-30
Complete history	See info



Registration #1	2008-03-13	11 mi
Registration #2	2011-03-15	69.914 mi
Registration #3	2011-03-17	69.923 mi
Registration #4	2012-03-19	85.542 mi
Registration #5	2013-03-15	98.594 mi
Registration #6	2014-03-13	109.716 mi
Registration #7	2015-03-09	121.028 mi
Registration #8	2016-03-29	133.562 mi
Registration #9	2016-03-29	133.562 mi
Registration #10	2016-03-29	133.562 mi
Registration #11	2016-03-29	133.562 mi
Registration #12	2016-03-29	133.562 mi
Registration #13	2016-03-29	133.562 mi
Registration #14	2016-03-29	133.562 mi
Registration #15	2016-03-29	133.562 mi
Registration #16	2016-03-29	133.562 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Kerb weight	1416 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	BLS 896160