



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Silver
Year of manufacture	-
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #12	2020-10-16 10:15
MOT test number	448925194512
Result	✓ Passed
Next expiry date	2021-10-15

MOT #11	2020-10-10 11:00
MOT test number	661255070796
Result	✗ Failed
MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))	

MOT #10	2019-04-23 10:21
MOT test number	635237321626
Result	✓ Passed

MOT #9	2018-03-27 09:18
MOT test number	441364950459
Result	✓ Passed

MOT #8	2018-03-27 09:18
MOT test number	202886265087
Result	✗ Failed
Pass with rectification Front registration plate deteriorated (6.3.1d)	

MOT #7	2017-04-22 13:16
MOT test number	509936210595
Result	✓ Passed

**MOT #6** 2016-06-06 13:59**MOT test number** 165662813370**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush rear console bush (2.4.G.2)**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush rear console bush (2.4.G.2)**MOT #5** 2015-06-10 14:34**MOT test number** 795221965118**Result** ✓ Passed**Advice** Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-06-10 14:49**MOT test number** 816721464179**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-06-10 12:22**MOT test number** 649101463107**Result** ✓ Passed



MOT #2 2012-06-11 13:02

MOT test number 185733162130

Result ✓ Passed

- Notice** Front wipers smear
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1 2011-06-15 09:56

MOT test number 209356661132

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 MT08OPL
Plate since	2024-03-28
Current registration	 MT08OPL
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-06-14
Last registration	2020-10-16
Complete history	See info



Registration #1	2008-06-14	26 mi
Registration #2	2011-06-15	18.817 mi
Registration #3	2012-06-11	23.951 mi
Registration #4	2013-06-10	28.182 mi
Registration #5	2014-06-10	32.658 mi
Registration #6	2015-06-10	40.587 mi
Registration #7	2016-06-06	48.963 mi
Registration #8	2019-06-06	55.277 mi
Registration #9	2019-06-06	55.277 mi
Registration #10	2019-06-06	55.277 mi
Registration #11	2019-06-06	55.277 mi
Registration #12	2019-06-06	55.277 mi
Registration #13	2019-06-06	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

BBM173167