





General information

Make	MAZDA
Model	MX-5 RF SPORT NAV
Colour	Red
Year of manufacture	2017
Top speed	133 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G







Internet history	
Entry 2	
Date	2021-07-11
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-07-10
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #6		2023-05-31 15:43
MOT test	number	549659017349
Result		✓ Passed
Next expi	ry date	2024-06-07
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Advice Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously v	veakened (1.1.14 (a) (ii))





MOT #5	2023-05-31 13:24	
MOT test number	403473760033	
Result	🗙 Failed	
Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))	
Advice Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
DANGEROUS Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)))	
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))	
Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
DANGEROUS Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		

MOT #4	2022-05-13 11:05
MOT test number	138525199531
Result	✓ Passed
MOT #3	2021-05-17 09:47
MOT test number	586108637675
Result	🗸 Passed
MOT #2	2020-06-08 09:13
MOT test number	419488320166
Result	🗸 Passed
MOT #1	2020-04-06 14:55
MOT test number	719045096814
Result	✓ Passed
Advice COVID-19 6 MONTH EXTENSION	



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 January 2025	Expires: 7 June 2024
Tax status	Valid until 1 January
Days left	246
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF CONTRACTOR OF CONTRA	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-04-12
Last registration	2023-05-31
Complete history	<u>See info</u>



Registration #1	2017-04-12	28 mi
Registration #2	2020-06-08	6.506 mi
Registration #3	2021-05-17	7.035 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.117 esi





Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1735 mm
Height	1235 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1045 kg
Max. allowed weight	1295 kg
Additional information	
Additional information Fuel tank capacity	45
	45 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 2