




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1	
Date	2022-02-23
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-01-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	63
Total items failed	5

MOT #16	2022-01-22 09:44
MOT test number	537139423476
Result	✓ Passed
Next expiry date	2023-01-21
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15	2022-01-21 11:42
MOT test number	413754845009
Result	✗ Failed
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))



MOT #14

2021-03-19 16:19

MOT test number

638664260753

Result

✓ Passed

- Advice

UNDERTRAY/ENGINE COVER FITTED
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Brake hose has slight corrosion to ferrule BOTH (1.1.12 (f) (i))
- Advice

Vehicle undersealed not allowing full inspection
- Advice

Child Seat fitted not allowing full inspection of adult belt
- Advice

Front Coil spring corroded BOTH (5.3.1 (b) (i))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13**

2021-03-19 14:27

MOT test number

397510765410

Result**✗ Failed**

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** UNDERTRAY/ENGINE COVER FITTED
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake hose has slight corrosion to ferrule BOTH (1.1.12 (f) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Front Coil spring corroded BOTH (5.3.1 (b) (i))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Vehicle undersealed not allowing full inspection
- DANGEROUS** Offside Brake pipe leaking on a hydraulic braking system front next to joint on front to rear (1.1.11 (b) (ii))
- MAJOR** Brake performance not tested due to brake pipe (1.2.1 (g))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12

2020-03-10 10:20

MOT test number

214957106621

Result**✓ Passed**

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** VEHICLE UNDERSEALED
- Advice** EXHAUST CORRODED
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #11	2019-03-16 09:50
MOT test number	294576374311
Result	✓ Passed
Advice	Exhaust corroded
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10	2018-03-23 12:16
MOT test number	974909600653
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit INNER EDGES (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit INNER EDGES (4.1.E.1)
Advice	Front Sub-frame corroded but not seriously weakened (2.4.G.1)
Advice	N/s rear tyre worn uneven

MOT #9	2017-03-25 09:28
MOT test number	997047940092
Result	✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
Advice	Brake pipe slightly corroded FRONT TO REAR (3.6.B.2c)

MOT #8	2016-04-01 09:25
MOT test number	562207339180
Result	✓ Passed
Advice	EXHAUST CORRODED
Advice	Brake pipe slightly corroded FRONT TO REAR X2 (3.6.B.2c)

**MOT #7** 2015-04-09 13:06**MOT test number** 495379195097**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Exhaust corroded**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2015-04-09 10:36**MOT test number** 608619895031**Result** ✗ Failed**Notice** Exhaust corroded**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-04-04 15:17**MOT test number** 507984494057**Result** ✓ Passed**Notice** All four tyres are perished**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Exhaust corroded

**MOT #4**

2014-04-03 10:10

MOT test number

959453894013

Result**✗ Failed****Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** Exhaust corroded**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** All four tyres are perished**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**MOT #3**

2013-04-11 08:37

MOT test number

897201903179

Result**✓ Passed****Advice** Nearside Front coil spring corroded (2.4.C.1b)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front coil spring corroded (2.4.C.1b)**Notice** Under-trays fitted obscuring some underside components**MOT #2**

2012-05-01 12:03

MOT test number

617342122125

Result**✓ Passed****Notice** Rear discs corroded**MOT #1**

2011-03-22 13:42

MOT test number

237231881050

Result**✓ Passed**



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2022

X

MOT

Expired:
21 January 2023

Tax status	Expired at 1 April 2022
Days left	760 days too late
MOT expiry date	21 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KY08SVX
Plate since	2019-09-29
Current registration	 KY08SVX
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-01
Last registration	2022-01-22
Complete history	See info



Registration #1	2008-03-01	18 mi
Registration #2	2011-03-22	19.071 mi
Registration #3	2012-05-01	23.643 mi
Registration #4	2013-04-11	29.839 mi
Registration #5	2014-04-03	36.155 mi
Registration #6	2014-04-04	36.158 mi
Registration #7	2015-04-09	42.804 mi
Registration #8	2015-04-09	42.804 mi
Registration #9	2016-04-01	48.279 mi
Registration #10	2016-04-01	48.279 mi
Registration #11	2016-04-01	48.279 mi
Registration #12	2016-04-01	48.279 mi
Registration #13	2016-04-01	48.279 mi
Registration #14	2016-04-01	48.279 mi
Registration #15	2016-04-01	48.279 mi
Registration #16	2016-04-01	48.279 mi
Registration #17	2016-04-01	48.279 mi
Registration #18	2016-04-01	48.279 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564