




report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 C/C CDTI
Colour	White
Year of manufacture	2015
Top speed	80 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-27
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	14
Total items failed	12

MOT #8	2023-11-27 11:44
MOT test number	462920987775
Result	✓ Passed
Next expiry date	2024-11-27

MOT #7	2022-11-28 10:31
MOT test number	518891571519
Result	✓ Passed

MOT #6	2021-10-22 11:45
MOT test number	687329165388
Result	✓ Passed

**MOT #5** 2020-08-10 13:07**MOT test number** 717026208421**Result** ✓ Passed

- Advice** Wiper blades worn but meet requirements
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** High level rear lamp not working/poss disconnected
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald outer edge (5.2.3 (e))
- Advice** Brake pedal rubber worn but meets requirements
- Advice** Service light on/warning message
- Advice** Rear suspension sitting down on assisters

MOT #4 2019-08-02 09:17**MOT test number** 798379149573**Result** ✓ Passed**MOT #3** 2019-07-23 08:32**MOT test number** 902159694634**Result** ✗ Failed

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Windscreen damaged and affecting the driver's view of the road crack zone b (3.2 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Side repeater not working mirror (4.4.1 (a) (ii))
- Fail** Windscreen washer not working (3.5 (a))

**MOT #2** 2018-08-09 13:32**MOT test number** 846526099331**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside safety bar damaged**Advice** Nearside Front Side repeater slightly discoloured leans broken (4.4.3 (a))**MOT #1** 2018-08-08 09:08**MOT test number** 874984827649**Result** ✗ Failed**Advice** Nearside Front Side repeater slightly discoloured leans broken (4.4.3 (a))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Side repeater not working broken (4.4.1 (a) (ii))**Fail** Offside Front Position lamp not working side marker (4.2.1 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside safety bar damaged**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
27 November 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-08-14
Last registration	2023-11-27
Complete history	See info



Registration #1	2015-08-14	29 mi
Registration #2	2018-08-08	27.300 mi
Registration #3	2018-08-09	27.300 mi
Registration #4	2019-07-23	48.459 mi
Registration #5	2019-08-02	48.470 mi
Registration #6	2019-08-02	48.470 mi
Registration #7	2019-08-02	48.470 mi
Registration #8	2019-08-02	48.470 mi
Registration #9	2019-08-02	48.470 mi
Registration #10	2019-08-02	48.470 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2070 mm
Height	2258 mm
Length	6293 mm
Wheel base	4332 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	M9T -C159796 LWL