



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO GBT
Colour	Black
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	123 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-19
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-24
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	29
Total items failed	1

MOT #12	2023-08-23 09:56
MOT test number	842300656956
Result	✓ Passed
Next expiry date	2024-08-24
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #11	2023-08-23 09:56
MOT test number	116720319503
Result	✗ Failed
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #10	2022-08-25 16:10
MOT test number	198144841590
Result	✓ Passed
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2022-08-25 12:35**MOT test number** 136771102323**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2021-08-25 14:58**MOT test number** 935685823926**Result** ✓ Passed**MOT #7** 2021-08-19 16:31**MOT test number** 332248715146**Result** ✗ Failed**DANGEROUS** Front Inner Brake disc in such a condition that it is seriously weakened both sides (1.1.14 (a) (ii))**Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**DANGEROUS** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pipe corroded, covered in grease or other material both sides under wing (1.1.11 (c))

**MOT #6**

2021-03-04 15:41

MOT test number

430445351346

Result

✓ Passed

Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Outer Integral body structure is deformed but structural rigidity is not significantly reduced sill (6.1.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5**

2021-03-04 08:21

MOT test number

719913251431

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Outer Integral body structure is deformed but structural rigidity is not significantly reduced sill (6.1.1 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4**

2020-02-22 08:00

MOT test number

934296866939

Result

✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))



MOT #3	2019-02-28 12:07
MOT test number	585896591013
Result	✓ Passed
MOT #2	2018-03-07 12:46
MOT test number	438214865096
Result	✓ Passed
MOT #1	2016-09-24 09:27
MOT test number	345538810689
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
24 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-26
Last registration	2023-08-23
Complete history	See info



Registration #1	2013-09-26	26 mi
Registration #2	2016-09-24	28.891 mi
Registration #3	2018-03-07	40.250 mi
Registration #4	2019-02-28	53.731 mi
Registration #5	2020-02-22	62.697 mi
Registration #6	2021-03-04	67.216 mi
Registration #7	2021-03-04	67.216 mi
Registration #8	2023-08-23	67.216 mi
Registration #9	2023-08-23	67.216 mi
Registration #10	2023-08-23	67.216 mi
Registration #11	2023-08-23	67.216 mi
Registration #12	2023-08-23	67.216 mi
Registration #13	2023-08-23	67.216 mi
Registration #14	2023-08-23	67.216 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	0533163