



KRI8XPC

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ5 BOOSTERJET SHVS
Colour	Red
Year of manufacture	2018
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	160 Nm at 1.700 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Hybrid / Electric
Consumption city	65.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	65.7 mpg
CO2 emission	97 g/km
CO2 label	A






Internet history

Entry 2


Date	2023-02-18
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	31
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-04-29
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #4	2024-04-15 12:11
MOT test number	498004726785
Result	✓ Passed
Next expiry date	2025-04-29

MOT #3	2023-04-24 11:07
MOT test number	663307847796
Result	✓ Passed

MOT #2	2022-04-29 13:56
MOT test number	962304159498
Result	✓ Passed

**MOT #1**

2021-04-30 10:07

MOT test number

354109384423

Result

✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking in tread inner and outer edges (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking in tread inner and outer edges (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges worn low (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn and heavy lipped inner face (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread inner and outer edges (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread inner and outer edges (5.2.3 (d) (ii))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges worn low (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn and heavy lipped (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
29 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	E
First licence fee (12 months)	£ 155,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	KR18XPC
Plate since	2019-03-29
Current registration	KR18XPC
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-04-20
Last registration	2024-04-15
Complete history	See info



Registration #1	2018-04-20	18 mi
Registration #2	2021-04-30	18.991 mi
Registration #3	2022-04-29	68.458 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	88%
Children	75%
Pedestrian	69%
Safety systems	44%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1480 mm
Length	3840 mm
Wheel base	2450 mm
Kerb weight	875 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K10C-1084211