





report date: 2024-03-28

General information

| Make | LAND ROVER |
|---------------------|----------------------------|
| Model | RANGE ROVER SPORT SDV6 HSE |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 130 mph |
| 0 - 100 km/h | 7.2 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 225 kW / 306 HP / 306 BHP |
|-------------------------|---------------------------|
| Max. torque | 700 Nm at 1.500 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/11



CU17ZPG

report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-01

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-10-07 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 7 |
| Total items failed | 0 |

| MOT #5 | | 2023-09-22 12:12 |
|--|--|------------------|
| MOT test | number | 763549083942 |
| Result | | ✓ Passed |
| Next exp | iry date | 2024-10-07 |
| Advice | Rear ACE pipes corroded | |
| Advice Driver's view Items removed from driver's view prior to test camera obstructing drivers view (3.1 (a) (ii)) | | |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #4 | | 2022-10-07 13:11 |
|----------|--|------------------|
| MOT test | number | 646353112335 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | 2021-10-08 08:44 |
|-----------------|------------------|
| MOT test number | 806306653100 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



CU17ZPG

report date: 2024-03-28

MOT #2 2021-03-15 15:46

MOT test number 532833979988

Result ✓ Passed

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view Chip in windscreen nsf (not affecting drivers view) (3.2 (a) (i))

MOT #1 2020-07-23 09:31

MOT test number 585326269439

Result ✓ Passed

Advice

COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 156 |
| MOT expiry date | 7 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| - | |
|--|--------------|
| Vehicle class | 49 |
| Band | J |
| First licence fee (12 months) | £ 1.040,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 1.565,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| manana and a second a second and a second an | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this LAND ROVER had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



CU17ZPG

report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-07-31 |
| Last registration | 2023-09-22 |
| Complete history | See info |



| Registration #1 | 2017-07-31 | 8 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-03-15 | 62.384 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 84% |
| Pedestrian | 63% |
| Safety systems | 86% |
| Overall rating | 84% |
| Video | see crash video |



Dimensions & weight

| Width | 2220 mm |
|---------------------|---------|
| Height | 1801 mm |
| Length | 4856 mm |
| Wheel base | 2923 mm |
| Kerb weight | 2115 kg |
| Max. allowed weight | 3050 kg |

Additional information

| Fuel tank capacity | 89 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1085520306DT |

CarCheck.co.uk page 11/11