





report date: 2024-03-29

General information

Make	BMW
Model	X1 SDRIVE18D SPORT
Colour	White
Year of manufacture	2018
Top speed	127 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-10-15

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-10-15

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



LS680HH report date: 2024-03-29

MOT history

MOT expiry date	2024-11-15
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #5	2023-11-16 12:02
MOT test number	746196400708
Result	✓ Passed
Next expiry date	2024-11-15
Advice Offside Front Lower Suspension arm pin or bush worn but not result (5.3.4 (a) (i)) Advice Nearside Front Lower Suspension arm pin or bush worn but not result (5.3.4 (a) (i))	

MOT #4	2023-11-15 12:41	
MOT test number	262373432073	
Result	× Failed	
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))		
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Front Lower Suspension arm pin or bush v (5.3.4 (a) (i))	worn but not resulting in excessive movement	

CarCheck.co.uk page 3/11



LS68OHH

report date: 2024-03-29

MOT test number

Result

Advice Items removed from driver's view prior to test

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge VERY CLOSE ON LIMITS (5.2.3 (e))

MOT test number

288750688163

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Items removed from driver's view prior to test

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge VERY CLOSE ON LIMITS (5.2.3 (e))

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



LS68OHH

report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



LS680HH report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

_	
Owner	history
OWILL	1113601

For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-10-08
Last registration	2023-11-16
Complete history	See info



Registration #1	2018-10-08	21 mi
Registration #2	2021-09-23	59.393 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71,777 es

More info >

CarCheck.co.uk page 10/11



LS68OHH

report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1821 mm
Height	1598 mm
Length	4439 mm
Wheel base	2670 mm
Kerb weight	1470 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles2Engine number54315440