





General information

Make	FIAT
Model	BRAVO SPORT TJET
Colour	Blue
Year of manufacture	-
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP	0 < 101 A
Max. torque	206 Nm at 2.250 rpm	101 - 120 B
Cylinders	4	121 - 140 E
Fuel type	Petrol	141 - 165 F
Consumption city	30.4 mpg	166 - 185 H
Consumption extra urban	48.7 mpg	186 - 225 J
Consumption combined	39.8 mpg	225+ L





Internet history	
Entry 1	
Date	2021-06-14
Pictures	1
Listing price	View report



source: autotrader.co.uk





MOT historyMOT #132020-12-28 14:49MOT test number278663236591Result✓ PassedNext expiry date2022-01-01

MOT #12	2020-01-02 15:09
MOT test number	249202140525
Result	✓ Passed

MOT #11		2019-12-24 15:12
MOT test	number	401288658062
Result		🗙 Failed
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
DANGER	Nearside Front Suspension arm ball joint likely to become detached (5.3.	.4 (a) (ii))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

МОТ #10	2018-04-11 16:01
MOT test number	347441671944
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #9	2016-10-17 15:47
MOT test number	773571166911
Result	✓ Passed



	report date: 2024-03-28	
MOT #8	2016-10-17 12:52	
MOT test number	390239685335	
Result	🗙 Failed	
Fail Parking brake: efficiency below requirements (3.7.B.7)		
Fail Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
MOT #7	2015-10-15 00.13	

MOT #7	2015-10-15 09:13
MOT test number	997803094357
Result	✓ Passed

MOT #6		2014-10-20 10:03
MOT test	number	336183494245
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2013-10-28 12:59
MOT test	number 689031303397
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Both rear tyres wearing low on inside edges

HW57HFH





MOT #4		2012-10-23 09:58
MOT test	number	368117392279
Result		✓ Passed
Notice	Nail in nearside rear tyre	
Notice	Both rear ryres worn on inner edge an getting low	
Notice	Under-trays fitted obscuring some underside components	
MOT #3		2011-10-15 10:43
MOT test	number	896268981285
Result		✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2010-10-12 12:12
MOT test number	350065880465
Result	✓ Passed

MOT #1	2010-10-12 11:31
MOT test number	680885580262
Result	🗙 Failed
Fail Nearside Front Tyre has a cut in excess of the requirements deep er (4.1.D.1a)	nough to reach the ply or cords
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.	.1)





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-10-19
Last registration	2020-12-28
Complete history	See info



Registration #1	2007-10-19	26 mi
Registration #2	2010-10-12	21.636 mi
Registration #3	2010-10-12	21.636 mi
Registration #4	2011-10-15	29.525 mi
Registration #5	2012-10-23	36.236 mi
Registration #6	2013-10-28	44.938 mi
Registration #7	2014-10-20	55.672 mi
Registration #8	2015-10-15	61.886 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg
Additional information	
Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	1153502