CAR CHECK

UK SHIOXCD

report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS
Colour	Red
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	157 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg



Internet history

Entry 1

Date	2021-10-24
Pictures	1
Listing price	View report

source: autotrader.co.uk

MOT history

MOT #13	2023-01-19 16:55
MOT test number	772203836088
Result	✓ Passed
Next expiry date	2024-01-18

MOT #12	2023-01-19 16:55
MOT test number	991070736372
Result	✗ Failed

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #11	2022-01-18 11:43
MOT test number	762163987076
Result	✓ Passed

MOT #10	2022-01-17 14:50
MOT test number	474339895198
Result	✗ Failed

DANGEROUS Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9	2020-12-08 10:30
MOT test number	288185561482
Result	✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2019-11-19 09:43
MOT test number	156907651505
Result	✓ Passed

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7	2018-12-10 11:53
MOT test number	178797696862
Result	✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6	2017-12-11 11:51
MOT test number	616582414140
Result	✓ Passed

MOT #5	2016-12-13 17:07
MOT test number	203973386067
Result	✓ Passed

MOT #4	2015-10-30 10:43
MOT test number	808753267923
Result	✓ Passed

MOT #3	2014-08-16 10:36
MOT test number	439268224233
Result	✓ Passed

Notice Both front tyres wearing on inner/outer shoulders

MOT #2	2013-08-20 10:11
MOT test number	569432333240
Result	✓ Passed

MOT #1	2013-05-29 11:20
MOT test number	247659743197
Result	✓ Passed

Notice Offside front droplink has slight movement at balljoints

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report here for more information.

More info

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ [illegible]
Auction value	£ [illegible]
Average private trade value	£ [illegible]

More info >

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here.

[redacted]	[redacted]
[redacted]	[redacted]
[redacted]	[redacted]
[redacted]	[redacted]
[redacted]	[redacted]
[redacted]	[redacted]

More info

Plate changes

See in this check if this KIA had different number plates.

[redacted]	[redacted]
[redacted]	UK [redacted]
[redacted]	[redacted]
[redacted]	UK [redacted]
[redacted]	[redacted]

More info

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report here and check if this KIA is financed.

Finance company	[redacted]
Date of agreement	[redacted]
Agreement type	[redacted]
Agreement term	[redacted]
Agreement number	[redacted]
Contact info	[redacted]

More info >

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-26
Last registration	2023-01-19
Complete history	See info



Registration #1	2010-05-26	24 mi
Registration #2	2013-05-29	8.385 mi
Registration #3	2013-08-20	9.038 mi
Registration #4	2014-08-16	20.838 mi
Registration #5	2015-10-30	30.953 mi
Registration #6	2016-12-13	36.821 mi
Registration #7	2017-12-11	38.846 mi
Registration #8	2018-12-10	40.579 mi
Registration #9	[redacted]	[redacted]
Registration #10	[redacted]	[redacted]
Registration #11	[redacted]	[redacted]
Registration #12	[redacted]	[redacted]
Registration #13	[redacted]	[redacted]
Registration #14	[redacted]	[redacted]
Registration #15	[redacted]	[redacted]

More info >

Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	[illegible]
S0482	[illegible]
S0501	[illegible]
S0566	[illegible]
S0567	[illegible]
S0569	[illegible]

View the complete KIA factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	★★★★☆
Video	see crash video

Dimensions & weight

Width	1820 mm
Height	1700 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FC8H600396