





report date: 2024-03-29

General information

Make	ТОУОТА
Model	CELICA VVTL-I GT
Colour	Silver
Year of manufacture	2006
Top speed	140 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	180 Nm at 6.800 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-07-17

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-18
Pictures	6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

Advice

MOT expiry date	2024-09-08
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	18
Total items failed	6

MOT #17		2023-09-09 10:26
MOT test	number	352021273191
Result		✓ Passed
Next expi	y date	2024-09-08
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #16	2022-07-02 11:20
MOT test number	215875356628
Result	✓ Passed
MOT #15	2021-06-18 17:51
MOT test number	451706832660

Result ✓ Passed

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #14	2020-07-13 16:29
MOT test number	692056764625
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #13 2020-07-13 12:31

MOT test number 388758539756

Result X Failed

Minor Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12 2019-06-29 10:50

MOT test number 456292501086

Result ✓ Passed

MOT #11 2018-06-29 15:24

MOT test number 889049346443

Result \(\sqrt{Passed} \)

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Items removed from driver's view prior to test

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Small chips to front windscreen not affecting drivers view

MOT #10 2017-07-05 14:58

MOT test number 708172459139

Result \rightarrow Passed

CarCheck.co.uk page 4/13



MOT #9 2017-07-04 15:18

MOT test number 552204569226

Result X Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #8 2016-06-28 12:19

MOT test number 672646842041

Result \rightarrow Passed

Advice Nearside rear tyre perished and cracking

Advice Under trays fitted obscuring some components

Advice Front brake discs are pitted and corroded on inner faces

MOT #7 2015-06-22 14:48

MOT test number 707633775160

Result
✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2014-07-09 13:46

MOT test number 107190994125

MOT #5 2013-07-09 09:03

MOT test number 708520593197

Result ✓ Passed

CarCheck.co.uk page 5/13



MOT #4		2012-07-16 09:05
MOT test	number	656818492191
Result		✓ Passed
Notice	Undertrays fitted.	
Notice	Tested wet	

MOT #3	2011-07-08 08:56
MOT test number	398119381108
Result	✓ Passed
Notice High travel on handbrake	

MOT #2	2010-07-16 10:58
MOT test number	330947190161
Result	✓ Passed
MOT #1	2009-07-21 15:58
MOT test number	361122409206
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	8 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here.	Α
nave: eneck it in the premium report and see all owner registrations. Download the fair report <u>nere</u> .	
THE STATE OF THE S	

More info >	>
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
NP2	
UK UK	
Plate since	
NK SIE	
Plate since	
More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-19
Last registration	2023-09-09
Complete history	See info



Registration #1	2006-07-19	7 mi
Registration #2	2009-07-21	25.425 mi
Registration #3	2010-07-16	29.537 mi
Registration #4	2011-07-08	33.149 mi
Registration #5	2012-07-16	37.453 mi
Registration #6	2013-07-09	41.081 mi
Registration #7	2014-07-09	46.850 mi
Registration #8	2015-06-22	55.183 mi
Registration #9	2016-06-28	59.826 mi
Registration #10	2017-07-04	63.770 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		91,709 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	2ZZ0167162

CarCheck.co.uk page 13/13