





General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM BLUE DRIVE
Colour	Black
Year of manufacture	2017
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н







Internet history


Entry 3

Date Pictures 2022-03-18

39

Listing price

View report



source: yesauto.com

Entry 2	
Date	2022-03-05
Pictures	3
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2022-02-06
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-16
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #6	2024-01-17 16:04
MOT test number	146792156717
Result	✓ Passed
Next expiry date	2025-01-16

MOT #5		2024-01-17 13:27
MOT test n	number	688683105517
Result		🗙 Failed
DANGER	OUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR	Offside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
DANGER	OUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR	Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
MAJOR	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)	(ii))

MOT #4	2023-01-10 09:03
MOT test number	766120465030
Result	✓ Passed
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	





MOT #3	2022-01-07 12:37
MOT test	number 839280382812
Result	✓ Passed
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #2	2021-01-12 11:49
MOT test number	516808719786
Result	✓ Passed

MOT #1	2020-01-16 12:34
MOT test	number 194424668927
Result	✓ Passed
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))



Tax & MOT check

Tax calculation

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 16 January 2025
Tax status	Valid until 1 January
Days left	248
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

and the second se	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-02-16
Last registration	2024-01-17
Complete history	See info



Registration #1	2017-02-16	19 mi
Registration #2	2020-01-16	31.272 mi
Registration #3	2021-01-12	34.379 mi
Registration #4	2022-01-07	36.840 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.300 est

More info >





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	2003 kg
Max. allowed weight	2600 kg
Additional information	
Fuel tank capacity	64
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Engine number

D4HBGU489081