





report date: 2024-03-29

General information

Make	RENAULT
Model	ZOE DYNAMIQUE INTENS
Colour	Black
Year of manufacture	2014
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	87 BHP	
Max. torque	ax. torque 220 Nm at 2.500 rpm	
Fuel type	Electricity	



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-10-16	
-----------------	--

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-15
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-06
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	5
Total items failed	8

MOT #10	2023-09-05 14:48
MOT test number	217264052742
Result	✓ Passed
Next expiry date	2024-09-06

MOT #9	2023-09-04 14:49
MOT test number	358995937688
Result	🗙 Failed
Advice Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2022-09-01 13:22
MOT test	number	235358974253
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-08-14 10:53
MOT test number	773755094007
Result	✓ Passed

CarCheck.co.uk page 3/12



Fail

Fail

ND64YJB

report date: 2024-03-29

MOT #6 2020-09-07 15:24 **MOT** test number 301754543583 Result ✓ Passed **MOT #5** 2020-08-29 10:02 **MOT** test number 590235912293 Result × Failed Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Fail Central Front Horn not working (7.7 (a) (ii)) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

 MOT #4
 2019-09-03 11:16

 MOT test number
 233159478671

 Result
 ✓ Passed

 MOT #3
 2019-08-31 09:14

 MOT test number
 528508001434

 Result
 X Failed

 Fail
 Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

 MOT #2
 2018-09-05 15:05

 MOT test number
 673331474305

 Result
 ✓ Passed

Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



MOT #1 2017-12-20 17:22

MOT test number 347110719775

Result ✓ Passed

CarCheck.co.uk page 5/12



6 September 2024

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this RENAULT had different number plates.	,	
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.	********	
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.	***************************************	
See in this check if this RENAULT had different number plates.		More info >
THE PARTY OF THE P	Plate changes	
Platte since	See in this check if this RENAULT had different number plates.	
Platte since	Number of plates	,
器 UK	Current registration	NK SIE
EN CONTRACTOR DE LA CON	Plate since	
Professional Control C	Current registration	NK NA
	Plate since	
More info >		More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-12-31
Last registration	2023-09-05
Complete history	See info



Registration #1	2014-12-31	11 mi
Registration #2	2017-12-20	22.712 mi
Registration #3	2018-09-05	25.668 mi
Registration #4	2019-08-31	34.786 mi
Registration #5	2019-09-03	34.920 mi
Registration #6	2020-08-29	46.951 mi
Registration #7	2020-09-07	46.951 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

60225	Air conditionir
60295	
60482	
0501	
0566	
0567	
0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1943 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12