




report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2014
Top speed	90 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-29
Pictures	45
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-20
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	31
Total items failed	7

MOT #12	2023-09-18 15:17
MOT test number	329816447837
Result	✓ Passed
Next expiry date	2024-09-20
Advice	Engine coolant below min mark in reservoir.
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #11	2022-09-21 15:11
MOT test number	704398896264
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2021-09-18 15:23
MOT test number	183378139799
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))



MOT #9	2021-03-25 14:17
MOT test number	534241782952
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8	2021-03-22 09:42
MOT test number	710618354863
Result	✗ Failed
MAJOR	Nearside Front Headlamp aim too high (4.1.2 (a))
MAJOR	Fuel system component leaking (6.1.3 (b) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front brake discs corroded

MOT #7	2020-03-18 17:12
MOT test number	783975584523
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Clutch anti slip rubber missing
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #6**

2020-03-12 10:11

MOT test number

608832266795

Result**✗ Failed**

- MAJOR** Offside Front Position lamp not working side light (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Hazard warning lamps inoperative (4.4.1 (e))
- Advice** Clutch anti slip rubber missing
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #5

2019-03-22 12:48

MOT test number

811575447028

Result**✓ Passed**

- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear tyre has flat spot
- Advice** Nearside Rear tyre has flat spot

MOT #4

2019-03-22 10:02

MOT test number

911934394355

Result**✗ Failed**

- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure Flat spot (5.2.3 (d) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure Flat spot (5.2.3 (d) (ii))

**MOT #3** 2018-03-15 14:33**MOT test number** 554333228436**Result** ✓ Passed**MOT #2** 2018-03-12 17:25**MOT test number** 195878579579**Result** ✗ Failed**Advice** Advise centre brake light inop**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Advise nearside rear side light broken**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #1** 2017-04-10 11:58**MOT test number** 416854653815**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-04-17
Last registration	2023-09-18
Complete history	See info



Registration #1	2014-04-17	11 mi
Registration #2	2017-04-10	37.752 mi
Registration #3	2018-03-12	50.013 mi
Registration #4	2018-03-15	50.018 mi
Registration #5	2019-03-22	60.726 mi
Registration #6	2019-03-22	60.730 mi
Registration #7	2020-03-12	72.735 mi
Registration #8	2020-03-22	72.737 mi
Registration #9	2020-03-22	72.737 mi
Registration #10	2020-03-22	72.737 mi
Registration #11	2020-03-22	72.737 mi
Registration #12	2020-03-22	72.737 mi
Registration #13	2020-03-22	72.737 mi
Registration #14	2020-03-22	72.737 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1673 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	JBDF0042531