



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-26
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-01-16
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	25
Total items failed	17

MOT #18	2024-01-16 12:59
MOT test number	287356540118
Result	✓ Passed
Next expiry date	2025-01-16
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2023-01-17 10:09
MOT test number	933550149874
Result	✓ Passed

MOT #16	2023-01-10 12:11
MOT test number	328301951042
Result	✗ Failed
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Offside Headlamp not working on main beam (4.1.1 (a) (ii))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**MOT #15**

2022-01-12 12:53

**MOT test number**

454518443699

**Result**

✓ Passed

**Minor**

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #14**

2020-11-11 15:36

**MOT test number**

866430396377

**Result**

✓ Passed

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice**

Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2020-11-11 09:11

**MOT test number**

412958521953

**Result**

✗ Failed

**Fail**

Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice**

Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Fail**

Nearside Front Outer Drive shaft flexible coupling excessively deteriorated (6.1.7 (d) (i))

**Fail**

Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #12**

2019-11-28 12:48

**MOT test number**

390646271561

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2019-11-26 11:18

**MOT test number**

981293507600

**Result**

✗ Failed

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10** 2018-11-30 15:07**MOT test number** 450535851367**Result** ✓ Passed**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))**Advice** Rear All direction indicators slightly discoloured Both (4.4.3 (a))**MOT #9** 2017-11-28 10:48**MOT test number** 399295799688**Result** ✓ Passed**MOT #8** 2016-11-23 11:54**MOT test number** 278912094637**Result** ✓ Passed**MOT #7** 2015-11-18 11:25**MOT test number** 355691917231**Result** ✓ Passed**MOT #6** 2015-11-17 14:44**MOT test number** 189106260575**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Front Suspension arm rubber bush deteriorated resulting in excessive movement o/s n/s (2.4.G.2)

**MOT #5** 2014-11-25 14:46**MOT test number** 328909924356**Result** ✓ Passed**MOT #4** 2013-11-07 14:29**MOT test number** 915621113359**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-11-07 14:29**MOT test number** 489841013307**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-12-03 11:16**MOT test number** 747248432331**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2011-12-03 10:25**MOT test number** 615147231356**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
16 January 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	16 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-01-19
Last registration	2024-01-16
Complete history	<a href="#">See info</a>



Registration #1	2009-01-19	27 mi
Registration #2	2011-12-03	22.243 mi
Registration #3	2012-12-03	31.990 mi
Registration #4	2013-11-07	41.303 mi
Registration #5	2014-11-25	42.517 mi
Registration #6	2015-11-17	43.383 mi
Registration #7	2015-11-18	43.383 mi
Registration #8	2016-11-23	44.164 mi
Registration #9	2017-11-28	45.166 mi
Registration #10	2018-11-30	47.700 mi
Registration #11	2019-01-01	48.000 mi
Registration #12	2019-01-01	48.000 mi
Registration #13	2019-01-01	48.000 mi
Registration #14	2019-01-01	48.000 mi
Registration #15	2019-01-01	48.000 mi
Registration #16	2019-01-01	48.000 mi
Registration #17	2019-01-01	48.000 mi
Registration #18	2019-01-01	48.000 mi
Registration #19	2019-01-01	48.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629