



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Silver
Year of manufacture	2004
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-07-02
Pictures	32
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	32
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-11
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	41
Total items failed	15

MOT #25	2024-02-12 14:39
MOT test number	562699440971
Result	✓ Passed
Next expiry date	2025-02-11
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Surface corrosion on underside of vehicle

MOT #24	2024-02-06 09:51
MOT test number	893272722790
Result	✗ Failed
Fail	Nearside Rear Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #23** 2023-01-13 13:53**MOT test number** 712887608380**Result** ✓ Passed**Advice** Centre exhaust heat shield insecure**MOT #22** 2022-02-14 12:20**MOT test number** 916196338376**Result** ✓ Passed**MOT #21** 2022-02-10 15:02**MOT test number** 309303047052**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn front bush worn (5.3.4 (a) (i))**MOT #20** 2021-03-17 15:29**MOT test number** 588130273348**Result** ✓ Passed**Advice** Covers on sills not allowing full inspection**Advice** Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #19**

2021-03-02 15:46

MOT test number

726127801167

Result**✗ Failed****Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Covers fitted tp sills not allowing full inspections**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Brake pipe corroded, covered in grease or other material all metal (1.1.11 (c))**MOT #18**

2020-02-25 16:22

MOT test number

457841145900

Result**✓ Passed****Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Brake pipe corroded, covered in grease or other material all metal (1.1.11 (c))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Covers fitted to sills not allowing full inspection

**MOT #17**

2020-02-21 11:58

MOT test number

733354900875

Result**✗ Failed****Fail**

Exhaust shield missing where fitted as original equipment creating a risk of fire above tank area (6.1.3 (e))

Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice

Covers fitted to sills not allowing full inspection

Advice

Brake pipe corroded, covered in grease or other material all metal (1.1.11 (c))

Fail

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice

Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #16

2019-02-26 14:21

MOT test number

818651757259

Result**✓ Passed****Advice**

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

2019-02-26 10:35

MOT test number

519934836998

Result**✗ Failed****Fail**

Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail

Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2018-03-06 09:47

MOT test number

629253475382

Result

✓ Passed

Advice Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Front Brake pipe slightly corroded to rear main (3.6.B.2c)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #13**

2017-02-28 11:38

MOT test number

491253147286

Result

✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit inner tread (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #12**

2016-02-24 11:20

MOT test number

323216583083

Result

✓ Passed

Advice Items removed from drivers view prior to test

**MOT #11** 2015-02-25 13:16**MOT test number** 746156855027**Result** ✓ Passed

- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10 2014-02-28 14:32**MOT test number** 809979454063**Result** ✓ Passed**MOT #9** 2014-02-28 12:03**MOT test number** 869479054071**Result** ✗ Failed

- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #8 2013-03-01 14:00**MOT test number** 106810463098**Result** ✓ Passed**MOT #7** 2012-03-07 14:02**MOT test number** 287517762009**Result** ✓ Passed

**MOT #6** 2012-03-01 12:16**MOT test number** 215761962045**Result** ✗ Failed**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)**Notice** 2 x front brakes slightly binding on**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2011-02-28 14:37**MOT test number** 565919351000**Result** ✓ Passed**MOT #4** 2010-02-25 12:41**MOT test number** 490376650026**Result** ✓ Passed**MOT #3** 2009-02-24 10:59**MOT test number** 981745759010**Result** ✓ Passed**MOT #2** 2008-02-08 12:26**MOT test number** 420389338006**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Both front tyres worn on edges**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2007-02-26 09:29**MOT test number** 601427257055**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-03-01
Last registration	2024-02-12
Complete history	See info



Registration #1	2004-03-01	19 mi
Registration #2	2007-02-26	24.818 mi
Registration #3	2008-02-08	33.449 mi
Registration #4	2009-02-24	39.876 mi
Registration #5	2010-02-25	46.218 mi
Registration #6	2011-02-28	51.768 mi
Registration #7	2012-03-01	56.375 mi
Registration #8	2012-03-07	56.375 mi
Registration #9	2013-03-01	58.822 mi
Registration #10	2014-02-28	61.752 mi
Registration #11	2014-02-28	61.752 mi
Registration #12	2015-02-25	65.105 mi
Registration #13	2016-02-24	68.662 mi
Registration #14	2017-02-28	71.518 mi
Registration #15	2018-02-28	75.375 mi
Registration #16	2019-02-28	79.232 mi
Registration #17	2020-02-28	83.089 mi
Registration #18	2021-02-28	86.946 mi
Registration #19	2022-02-28	90.803 mi
Registration #20	2023-02-28	94.660 mi
Registration #21	2024-02-12	98.517 mi
Registration #22	2024-02-12	98.517 mi
Registration #23	2024-02-12	98.517 mi
Registration #24	2024-02-12	98.517 mi
Registration #25	2024-02-12	98.517 mi
Registration #26	2024-02-12	98.517 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

Engine number	3ZZ1648984
---------------	------------