



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-04-05
Pictures	29
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-30
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	7
Total items failed	1

MOT #13	2023-05-31 14:22
MOT test number	576612590461
Result	✓ Passed
Next expiry date	2024-05-30

MOT #12	2022-09-08 14:29
MOT test number	423967697995
Result	✓ Passed

MOT #11	2021-09-16 09:48
MOT test number	373154697865
Result	✓ Passed

MOT #10	2021-09-16 09:48
MOT test number	227437820722
Result	✗ Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9	2020-09-17 14:50
MOT test number	184172445648
Result	✓ Passed

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

**MOT #8** 2020-09-17 09:31**MOT test number** 116692876813**Result** ✗ Failed**Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #7** 2019-09-10 12:16**MOT test number** 262884334297**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both worn on inner edge (5.2.3 (e))**MOT #6** 2018-08-24 10:06**MOT test number** 909792886259**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))**MOT #5** 2017-09-01 10:56**MOT test number** 709458129607**Result** ✓ Passed**MOT #4** 2016-09-01 12:30**MOT test number** 483288740682**Result** ✓ Passed**MOT #3** 2015-09-10 11:19**MOT test number** 474052392240**Result** ✓ Passed



MOT #2	2014-09-04 09:22
MOT test number	885547544220
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-09-12 11:43
MOT test number	338075753496
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
30 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	30 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YG60FSE
Plate since	2019-09-28
Current registration	YG60FSE
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-18
Last registration	2023-05-31
Complete history	See info



Registration #1	2010-09-18	20 mi
Registration #2	2013-09-12	15.177 mi
Registration #3	2014-09-04	20.279 mi
Registration #4	2015-09-10	25.269 mi
Registration #5	2016-09-01	29.850 mi
Registration #6	2017-09-01	34.860 mi
Registration #7	2018-08-24	38.671 mi
Registration #8	2019-09-10	42.134 mi
Registration #9	2020-05-31	45.000 mi
Registration #10	2021-05-31	45.000 mi
Registration #11	2022-05-31	45.000 mi
Registration #12	2023-05-31	45.000 mi
Registration #13	2024-03-28	45.000 mi
Registration #14	2024-03-28	45.000 mi
Registration #15	2024-03-28	45.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1382 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	957548