



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ3 DDIS
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-05-21
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-11-08
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	28
Total items failed	1

MOT #12 2023-11-08 11:02**MOT test number** 445106981770**Result** Passed**Next expiry date** 2024-11-08

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Upper Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** General corrosion advise

MOT #11 2022-11-07 12:32**MOT test number** 305992965529**Result** Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge and offside front (5.2.3 (e))

MOT #10 2021-11-09 12:22**MOT test number** 963933006973**Result** Passed

- Advice** Nearside Front Inner Play in steering rack inner joint(s)



MOT #9	2021-11-09 11:21
MOT test number	670232566069
Result	✗ Failed
MAJOR	Nearside Front Inner Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
Advice	Nearside Front Inner Play in steering rack inner joint(s)

MOT #8	2020-11-03 17:15
MOT test number	187828206044
Result	✓ Passed
Advice	Steering and suspension components corroded
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 185/55/16 (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7	2020-10-30 12:33
MOT test number	253463028630
Result	✗ Failed
MAJOR	Brake pipe excessively corroded both front to rears (1.1.11 (c))
MAJOR	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Brake pipe excessively corroded both front (1.1.11 (c))
Advice	Steering and suspension components corroded
MAJOR	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 185/55/16 (5.2.3 (e))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #6** 2019-03-29 16:29**MOT test number** 573258917650**Result** ✓ Passed**MOT #5** 2018-04-05 08:26**MOT test number** 883394190249**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Play in steering rack inner joint(s)**MOT #4** 2018-04-05 08:26**MOT test number** 377428042876**Result** ✗ Failed**Advice** Nearside Play in steering rack inner joint(s)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2017-04-25 14:42**MOT test number** 303659111571**Result** ✓ Passed**MOT #2** 2015-11-24 09:22**MOT test number** 704262172438**Result** ✓ Passed**Advice** Offside Front Bumper damage**Advice** Windscreen chipped



MOT #1	2014-11-18 09:24
MOT test number	506082924398
Result	✓ Passed
<div>Notice Both rear tyre treads cracked</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-09
Last registration	2023-11-08
Complete history	See info



Registration #1	2011-12-09	7 mi
Registration #2	2014-11-18	40.026 mi
Registration #3	2015-11-24	52.737 mi
Registration #4	2017-04-25	61.799 mi
Registration #5	2018-04-05	76.232 mi
Registration #6	2018-04-05	76.232 mi
Registration #7	2019-03-29	89.390 mi
Registration #8	2019-03-29	89.390 mi
Registration #9	2019-03-29	89.390 mi
Registration #10	2019-03-29	89.390 mi
Registration #11	2019-03-29	89.390 mi
Registration #12	2019-03-29	89.390 mi
Registration #13	2019-03-29	89.390 mi
Registration #14	2019-03-29	89.390 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1170 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	D13A-1615222