



PJ08DHM

report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Red
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-09-06
Pictures	38
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-01
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	32
Total items failed	8

MOT #16	2023-10-02 09:17
---------	------------------

MOT test number	908899088737
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-01
------------------	------------

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases flexi and rear box - outer skin peeling (6.1.2 (a))
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. front & rear 40% (1.2.1 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #15**

2023-10-02 09:17

MOT test number

755077725713

Result**✗ Failed****Pass with rectification** Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases flexi and rear box - outer skin peeling (6.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. front & rear 40% (1.2.1 (b) (i))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MOT #14**

2022-09-10 09:08

MOT test number

238403734325

Result**✓ Passed****Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))**Advice** Offside Rear handbrake performance poor**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #13** 2021-09-09 14:32**MOT test number** 398561880017**Result** ✓ Passed**MOT #12** 2020-09-29 14:01**MOT test number** 639381917414**Result** ✓ Passed**MOT #11** 2019-03-19 16:25**MOT test number** 943062362074**Result** ✓ Passed**MOT #10** 2019-03-19 11:23**MOT test number** 572389294920**Result** ✗ Failed**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2018-03-27 10:22**MOT test number** 975301822025**Result** ✓ Passed**MOT #8** 2017-03-23 11:42**MOT test number** 905989257318**Result** ✓ Passed

**MOT #7** 2016-03-30 11:40**MOT test number** 436950677885**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit sidewalls perished and nail in tread (4.1.E.1)**Advice** Oil leak. breather pipe detached**MOT #6** 2016-03-23 12:31**MOT test number** 450020740428**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit sidewalls perished and nail in tread (4.1.E.1)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Oil leak. breather pipe detached**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-03-05 10:45**MOT test number** 309544665019**Result** ✓ Passed**Notice** Front pads worn**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Os rear seat back catch faulty**MOT #4** 2014-03-11 11:22**MOT test number** 555460174074**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2013-03-26 12:30**MOT test number** 386435183023**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-03-10 09:19**MOT test number** 849340972019**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-03-11 10:11**MOT test number** 275170171023**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
1 October 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-31
Last registration	2023-10-02
Complete history	See info



Registration #1	2008-03-31	28 mi
Registration #2	2011-03-11	16.170 mi
Registration #3	2012-03-10	21.509 mi
Registration #4	2013-03-26	28.524 mi
Registration #5	2014-03-11	32.587 mi
Registration #6	2015-03-05	36.613 mi
Registration #7	2016-03-23	42.716 mi
Registration #8	2017-03-20	35.377 mi
Registration #9	2018-03-20	35.377 mi
Registration #10	2019-03-20	35.377 mi
Registration #11	2020-03-20	35.377 mi
Registration #12	2021-03-20	35.377 mi
Registration #13	2022-03-20	35.377 mi
Registration #14	2023-10-02	35.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4363732