





report date: 2024-03-28

General information

Make	JAGUAR
Model	F-PACE PRESTIGE
Colour	Grey
Year of manufacture	2018
Top speed	129 mph
0 - 60 mph	8.0 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	430 Nm at 2.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-05

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-18
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #5		2024-04-26 14:56
MOT test	number	485445537133
Result		X Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both seats	
MAJOR	Offside Front Daytime running lamp not working (4.2.1 (a) (ii))	

MOT #4	2023-05-17 11:03
MOT test number	847202286009
Result	✓ Passed
Advice Items removed from driver's view prior to test	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

898005212410

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear exhaust heat shield insecure

Advice Central Exhaust mounting defective rubber mount badly split (6.1.2 (a))

MOT #2 2022-05-14 13:18 **MOT** test number 905288131458 Result × Failed **Advice** Rear exhaust heat shield insecure **MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Central Exhaust mounting defective rubber mount badly split (6.1.2 (a)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1	2021-05-14 14:40
MOT test number	905607597466
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



door of plates

factor scincore

LM18EXW

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this JAGUAR had different number plates.

UK (

More info >



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-05-19
Last registration	2024-04-26
Complete history	See info



Registration #1	2018-05-19	19 mi
Registration #2	2021-05-14	86.097 mi
Registration #3		11.777 es
Registration #4	2022-05-14	92.021 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	93%
Children	85%
Pedestrian	80%
Safety systems	72%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2175 mm
Height	1667 mm
Length	4731 mm
Wheel base	2874 mm
Kerb weight	1720 kg
Max. allowed weight	2380 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	170925W0308204DTD

CarCheck.co.uk page 11/11