



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 8V DYNAMIC
Colour	Red
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-14
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-05-05
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	28
Total items failed	1

MOT #14 2024-04-16 09:57

MOT test number 210018384852

Result ✓ Passed

Next expiry date 2025-05-05

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13 2023-04-20 16:21

MOT test number 117169755981

Result ✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)
- Minor** Offside Front Headlamp lens slightly defective cloudy. (4.1.1 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Headlamp lens slightly defective cloudy. (4.1.1 (b) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12**

2023-04-17 13:33

MOT test number

525092642908

Result**✗ Failed**

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Headlamp lens slightly defective cloudy. (4.1.1 (b) (i))

MAJOR Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Offside Front Play in steering rack inner joint(s)

Minor Nearside Front Headlamp lens slightly defective cloudy. (4.1.1 (b) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #11

2022-05-06 12:26

MOT test number

107864744409

Result**✓ Passed****MOT #10**

2020-09-11 08:11

MOT test number

277624271512

Result**✓ Passed****MOT #9**

2019-06-24 09:53

MOT test number

575048841774

Result**✓ Passed**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2018-06-21 09:16**MOT test number** 493496495634**Result** ✓ Passed**MOT #7** 2017-06-28 11:17**MOT test number** 254908876098**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2017-06-28 11:17**MOT test number** 247227409153**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-08-17 10:07**MOT test number** 745427574360**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-08-12 11:11**MOT test number** 705914679495**Result** ✓ Passed

**MOT #3** 2014-08-06 10:17**MOT test number** 908998214288**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #2** 2013-09-10 10:36**MOT test number** 989583553218**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-09-26 15:58**MOT test number** 297620072290**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
5 May 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	5 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YX59XLC
Plate since	2019-03-29
Current registration	YX59XLC
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-07
Last registration	2024-04-16
Complete history	See info



Registration #1	2009-10-07	26 mi
Registration #2	2012-09-26	18.110 mi
Registration #3	2013-09-10	24.464 mi
Registration #4	2014-08-06	30.400 mi
Registration #5	2015-08-12	37.037 mi
Registration #6	2016-08-17	42.497 mi
Registration #7	2017-06-28	46.170 mi
Registration #8	2017-06-28	46.170 mi
Registration #9	2019-05-29	55.377 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1818 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4898929