



report date: 2024-03-28

General information

Make	SUZUKI
Model	IGNIS GL
Colour	Red
Year of manufacture	-
Top speed	99 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.100 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-12
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #14	2021-11-19 12:36
MOT test number	189742866308
Result	✓ Passed
Next expiry date	2022-11-18
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Coil spring corroded both side (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
Minor	Front Windscreen wiper blade defective both (3.4 (b) (i))
Advice	Front windscreen has stonechip but not adversely affecting driver's view

MOT #13	2020-10-22 09:14
MOT test number	923873221803
Result	✓ Passed

MOT #12	2019-08-17 08:53
MOT test number	948889946942
Result	✓ Passed
Minor	Horn not working properly (7.7 (a) (i))
Advice	Centre exhaust hanger broken

**MOT #11**

2018-08-16 11:56

MOT test number

939742261823

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre Outer Sidewall Perished
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Various Under Vehicle Corrosion
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10

2017-08-17 09:46

MOT test number

656235050851

Result

✓ Passed

- Advice** Rear coil spring corroded Both sides (2.4.C.1b)

MOT #9

2016-08-16 09:52

MOT test number

157791604776

Result

✓ Passed

- Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)
- Advice** Various under vehicle corrosion
- Advice** Offside Rear coil spring worn (2.4.C.1b)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear tyres sidewalls perished
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #8** 2015-08-15 11:59**MOT test number** 656287725231**Result** ✓ Passed**MOT #7** 2014-10-17 09:28**MOT test number** 757580994240**Result** ✓ Passed**MOT #6** 2014-02-20 08:48**MOT test number** 495551654002**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside front tyre on the limit**Advice** Rear coil spring corroded (2.4.C.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-03-04 16:17**MOT test number** 637943263027**Result** ✓ Passed**MOT #4** 2012-08-22 15:46**MOT test number** 868125932224**Result** ✓ Passed



MOT #3	2012-08-22 09:28
MOT test number	765045832200
Result	✗ Failed
Fail	Nearside Rear wheel bearing rough when rotated (2.6.1)
Fail	Nearside Rear wheel bearing has excessive play (2.6.2)

MOT #2	2011-09-13 10:15
MOT test number	448076951208
Result	✓ Passed

MOT #1	2010-09-17 09:22
MOT test number	542690660231
Result	✓ Passed



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	EK57CWO
Plate since	2019-09-28
Current registration	EK57CWO
Plate since	2019-09-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-28
Last registration	2021-11-19
Complete history	See info



Registration #1	2007-09-28	22 mi
Registration #2	2010-09-17	57.631 mi
Registration #3	2011-09-13	68.012 mi
Registration #4	2012-08-22	75.563 mi
Registration #5	2012-08-22	75.563 mi
Registration #6	2013-03-04	78.846 mi
Registration #7	2014-02-20	86.382 mi
Registration #8	2014-10-17	89.800 mi
Registration #9	2015-05-20	95.277 mi
Registration #10	2016-05-20	101.277 mi
Registration #11	2017-05-20	107.277 mi
Registration #12	2018-05-20	113.277 mi
Registration #13	2019-05-20	119.277 mi
Registration #14	2020-05-20	125.277 mi
Registration #15	2021-05-20	131.277 mi
Registration #16	2022-05-20	137.277 mi

More info >



Dimensions & weight

Width	1605 mm
Height	1555 mm
Length	3775 mm
Wheel base	2360 mm
Kerb weight	955 kg
Max. allowed weight	1470 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M13A-8008489