






General information

Make	FIAT
Model	PUNTO EASY
Colour	Blue
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	132 g/km
CO2 label	E







Internet history

Entry 2	
Date	2023-12-23
Pictures	10
Listing price	View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-11-03

View report

9

source: cargurus.co.uk









MOT history

MOT expiry date	2025-02-22
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	13
Total items failed	12

MOT #14	2024-02-23 14:25
MOT test number	909381303433
Result	✓ Passed
Next expiry date	2025-02-22
Advice Underbody scabby	

MOT #13	2023-10-21 11:34
MOT test	number 789617247331
Result	✓ Passed
Advice	Suspension component corroded but not seriously weakened Front and Rear (5.3.3 (b) (i))
Advice	Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #12	2023-10-18 16:57
MOT test number	960970850903
Result	🗙 Failed
Fail Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))	
Advice Suspension component corroded but not seriously weakened Front and Rear (5.3.3 (b) (i))	
Advice Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))	



ND62ZLE	
report date: 2024-03-28	3

MOT #11		2022-11-03 15:58
MOT test	number	556145335436
Result		✓ Passed
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Suspension component corroded but not seriously weakened Front suspension and sub-frame (5.3.3 (b) (i))		
MOT #10		2021-11-03 16:04

MOT test number 347573248557
Result Passed

МОТ #9	2021-01-14 15:53
MOT test number	467421114365
Result	✓ Passed

MOT #8	3	2021-01-12 10:30
MOT te	st number	217965127499
Result		🗙 Failed
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))	
Fail	Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	

MOT #7	2020-01-08 09:51
MOT test number	250790516618
Result	✓ Passed





MOT #6	2020-01-08 08:54
MOT test number	397401620967
Result	🗙 Failed
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2)	2 (c))
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
MOT #5	2019-01-07 15:26
MOT test number	715584984788
Result	🗸 Passed
MOT #4	2019-01-07 09:11
MOT test number	418069158136
Result	🗙 Failed
Fail Driver's view of the road through the swept area of the windscreen materially aff obstruction camera (3.1 (a) (ii))	fected by an
Fail Front Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail Nearside Rear Position lamp not working (4.2.1 (a))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	

MOT #3		2018-01-09 13:59
MOT test	number	990449257740
Result		✓ Passed
Advice	Front exhaust and rear box corroded	
Advice	Shock absorber has a light misting of oil both rear (2.7.3)	



Exhaust corroded

Advice



MOT #2		2017-01-10 11:40
MOT test nun	ıber	327610689671
Result		✓ Passed
	fside Rear Shock absorber has a light misting of oil (2.7.3) ar exhaust corroded	
MOT #1		2016-01-15 10:06
MOT test nun	ıber	213424886859
Result		✓ Passed



Tax & MOT check

Taxed Taxed 1 February 2025	✓ MOT Expires: 22 February 2025
Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-01-15
Last registration	2024-02-23
Complete history	See info



Registration #1	2013-01-15	13 mi
Registration #2	2016-01-15	26.331 mi
Registration #3	2017-01-10	38.533 mi
Registration #4	2018-01-09	49.305 mi
Registration #5	2019-01-07	58.559 mi
Registration #6	2019-01-07	58.559 mi
Registration #7	2020-01-08	68.077 mi
Registration #8	2020-01-08	68.077 mi
Registration #9	2021-01-12	77.081 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 esi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	0272619