



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 3


Date	2021-10-17
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 2



Date	2021-09-19
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-10
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-11-07
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	30
Total items failed	23

MOT #21 2023-11-07 17:07

MOT test number 415374579263

Result ✓ Passed

Next expiry date 2024-11-07

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #20 2023-11-03 12:28

MOT test number 752315644968

Result ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Anti-roll bar likely to become detached (5.3.3 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar likely to become detached (5.3.3 (a) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #19**

2022-11-08 16:53

**MOT test number**

598862413473

**Result**

✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #18**

2022-11-07 14:53

**MOT test number**

237250228140

**Result**

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2021-09-14 11:48

**MOT test number**

323235682259

**Result**

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #16**

2021-09-13 05:49

**MOT test number**

559999056223

**Result**

✗ Failed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))



**MOT #15** 2021-02-12 08:50**MOT test number** 634307827116**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-02-01 10:20**MOT test number** 310644361828**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-01-10 14:07**MOT test number** 239984696112**Result** ✓ Passed**MOT #12** 2019-01-30 14:10**MOT test number** 917179186519**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2019-01-30 10:58**MOT test number** 799100104557**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2018-02-01 09:46**MOT test number** 111573304342**Result** ✓ Passed**MOT #9** 2018-01-31 16:17**MOT test number** 861575081843**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 205/50/17 (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #8** 2017-01-12 14:33**MOT test number** 200144306736**Result** ✓ Passed**MOT #7** 2016-01-20 14:06**MOT test number** 720259685299**Result** ✓ Passed

**MOT #6** 2015-09-08 15:49**MOT test number** 207531078342**Result** ✓ Passed**MOT #5** 2015-09-08 15:49**MOT test number** 505017271505**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #4** 2015-02-06 17:56**MOT test number** 147467135000**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2015-02-06 13:05**MOT test number** 576697635020**Result** ✗ Failed**Advice** Offside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Brake pedal creeps down while the pedal is held under pressure (3.3.B.1a)**MOT #2** 2014-01-21 00:50**MOT test number** 149831924463**Result** ✓ Passed





MOT #1

2014-01-20 17:31

MOT test number

445540324003

Result

✗ Failed

Pass with rectification

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail

Parking brake lever has no reserve travel (3.1.6b)

Fail

Front Brakes imbalanced across an axle (3.7.B.5b)

Pass with rectification

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Pass with rectification

Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail

Front brake application uneven (3.7.B.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
7 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	7 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2011-01-06
Last registration	2023-11-07
Complete history	<a href="#">See info</a>



Registration #1	2011-01-06	6 mi
Registration #2	2014-01-20	61.005 mi
Registration #3	2014-01-21	61.008 mi
Registration #4	2015-02-06	64.903 mi
Registration #5	2015-02-06	64.903 mi
Registration #6	2015-09-08	67.783 mi
Registration #7	2015-09-08	67.783 mi
Registration #8	2016-01-20	69.411 mi
Registration #9	2017-01-12	75.713 mi
Registration #10	2018-01-31	82.578 mi
Registration #11	2018-02-01	82.580 mi
Registration #12	2019-01-30	87.147 mi
Registration #13	2019-01-30	87.148 mi
Registration #14	2019-01-30	87.148 mi
Registration #15	2019-01-30	87.148 mi
Registration #16	2019-01-30	87.148 mi
Registration #17	2019-01-30	87.148 mi
Registration #18	2019-01-30	87.148 mi
Registration #19	2019-01-30	87.148 mi
Registration #20	2019-01-30	87.148 mi
Registration #21	2019-01-30	87.148 mi
Registration #22	2019-01-30	87.148 mi
Registration #23	2019-01-30	87.148 mi
Registration #24	2019-01-30	87.148 mi
Registration #25	2019-01-30	87.148 mi



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	1760212