



report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ D V6 LUXURY
Colour	Black
Year of manufacture	2011
Top speed	155 mph
0 - 60 mph	6.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	271 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-11-16
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-22
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	36
Total items failed	7

MOT #12	2023-05-04 11:24
MOT test number	879669548211
Result	✓ Passed
Next expiry date	2024-05-22
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))

MOT #11	2022-05-23 14:40
MOT test number	247238019314
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Tyre pressure monitoring light on
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Power steering component has slight seepage from a component rack (2.1.5 (a))

**MOT #10** 2022-05-20 13:20**MOT test number** 350433240776**Result** ✗ Failed

- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Power steering component has slight seepage from a component rack (2.1.5 (a))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Tyre pressure monitoring light on
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #9** 2021-04-23 13:07**MOT test number** 905109165684**Result** ✓ Passed

- Advice** Rear Suspension bushes perishing
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Tyre pressure system light on
- Advice** Power steering ram has slight seepage from a joint (2.1.5 (a))

**MOT #8** 2020-03-25 15:35**MOT test number** 870305452701**Result** ✓ Passed

**MOT #7** 2019-03-21 14:48**MOT test number** 551612819932**Result** ✓ Passed**Advice** Slight tear in n/s/f tyre outer edge**Advice** O/s/r tyre wearing close to wear indicators**MOT #6** 2018-03-06 13:03**MOT test number** 490870295756**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-03-24 10:47**MOT test number** 579966990996**Result** ✓ Passed**MOT #4** 2015-11-19 15:30**MOT test number** 336764645547**Result** ✓ Passed**Advice** Offside Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front tyre has damage to sidewall**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre has a cut but not deep enough to reach the ply or cords



MOT #3	2015-04-08 08:38
MOT test number	167338195067
Result	✓ Passed
Notice	Power steering leak

MOT #2	2014-04-17 15:33
MOT test number	836937804110
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
Notice	Small cut to nearside front tyre outer wall
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2014-04-17 11:05
MOT test number	197477404177
Result	✗ Failed
Notice	Small cut to nearside front tyre outer wall
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>OV11KDF</b>
Plate since	2019-09-28
Current registration	<b>OV11KDF</b>
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-04-21
Last registration	2023-05-04
Complete history	<a href="#">See info</a>



Registration #1	2011-04-21	29 mi
Registration #2	2014-04-17	75.097 mi
Registration #3	2014-04-17	75.097 mi
Registration #4	2015-04-08	99.364 mi
Registration #5	2015-11-19	111.258 mi
Registration #6	2017-03-24	120.526 mi
Registration #7	2018-03-06	131.470 mi
Registration #8	2019-05-29	151.277 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi
Registration #14	2019-05-29	151.277 mi

More info >



Dimensions & weight

Width	2110 mm
Height	1448 mm
Length	5247 mm
Wheel base	3157 mm
Kerb weight	1813 kg
Max. allowed weight	2365 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	0504489306DT