





report date: 2024-03-29

General information

Make	SMART
Model	FORTWO COUPE PASSION 71
Colour	Silver
Year of manufacture	2008
Top speed	90 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	13.3 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/14



report date: 2024-03-29

✓ Passed

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

Result

MOT expiry date	2025-04-10
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	35
Total items failed	14

MOT #19		2024-04-11 12:35
MOT test i	number	878868256530
Result		✓ Passed
Next expir	y date	2025-04-10
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously w	veakened (1.1.14 (a) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material f	rom flexi (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material	front flexi (1.1.11 (c))
Advice	Front advise front suspension and components corroded	

MOT #18	2023-06-09 11:00
MOT test number	406642214089
Result	✓ Passed
MOT #17	2022-06-30 07:42
MOT test number	705082838285

MOT #16	2021-06-30 07:33
MOT test number	360598371996

Result Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT #15 2020-08-25 13:55

MOT test number 880608749732

Result ✓ Passed **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i)) Advice Rear Fuel filler cap seal perished Advice Offside Rear Upper Suspension spring mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i)) Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** Nearside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i)) Front Heavy corrosion on front steering and suspension components on both sides **Advice**

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #14 2020-08-12 15:22

MOT test number 701288818382

Result X Failed

Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Upper Suspension spring mounting prescribed area damaged but not considered excessive (5.3.6 (a) (i))

Fail Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Rear Fuel filler cap seal perished

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Upper Suspension spring mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Fail Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Front Heavy corrosion on front steering and suspension components on both sides

Fail Offside Front Macpherson strut top bush or bearing has excessive wear or free play Top mounting (5.3.4 (a) (i))

MOT #13 2019-04-15 09:46

MOT test number 627986451132

Result
✓ Passed

MOT #12 2018-04-17 16:45

MOT test number 656207670289

CarCheck.co.uk page 4/14



report date: 2024-03-29

× Failed

MOT #11 2018-04-16 09:04

MOT test number 608698449770

Result × Failed

Fail Nearside Rear Brake pipe excessively corroded from brake cylinder over suspension (3.6.B.2c)

Fail Offside Front coil spring broken (2.4.C.1a)

Offside Rear Brake pipe excessively corroded from brake cylinder over suspension (3.6.B.2c) Fail

MOT #10 2017-04-14 11:23

MOT test number 282408807333

Result ✓ Passed

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Offside Rear Brake pipe slightly corroded (3.6.B.2c) Advice

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9 2017-04-12 10:02

MOT test number 900214125103

Result

Service brake: efficiency below requirements (3.7.B.7)

Offside Rear rear brake binding (3.7.B.1)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

Fail Nearside Rear rear brake binding (3.7.B.1)

Fail

Fail

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8	2016-04-15 11:26
MOT test number	790483060841
Result	✓ Passed
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #7	2016-04-11 10:59
MOT test number	929486789028
Result	X Failed
Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Fail Offside rear brake binding (3.7.B.1)	
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	

MOT #6	2015-04-13 10:40
MOT test number	915213805109
Result	✓ Passed
MOT #5	2014-04-17 12:09
MOT test number	337247804178
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #4 2014-04-16 14:51

MOT test number 837046704155

Result X Failed

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Advise rear bumper loose

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

MOT #3 2013-06-06 13:03

MOT test number 558377853195

Result ✓ Passed

MOT #2 2012-06-19 11:58

MOT test number 999961472183

Result ✓ Passed


MOT #1 2011-06-28 14:21

MOT test number 159869871196

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory	
For how long did the current and previous owner(s) have this SMART? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manuse and the same and the sam	

	More info >
Plate changes	
See in this check if this SMART had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SMART is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-06-18
Last registration	2024-04-11
Complete history	See info



Registration #1	2008-06-18	15 mi
Registration #2	2011-06-28	13.342 mi
Registration #3	2012-06-19	20.433 mi
Registration #4	2013-06-06	25.368 mi
Registration #5	2014-04-16	29.821 mi
Registration #6	2014-04-17	29.821 mi
Registration #7	2015-04-13	30.987 mi
Registration #8	2016-04-11	31.565 mi
Registration #9	2016-04-15	31.570 mi
Registration #10	2017-04-12	31.898 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		77.777 au

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139

CarCheck.co.uk page 14/14