



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Silver
Year of manufacture	2008
Top speed	72 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	196 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-07-16
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-17
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	22
Total items failed	9

MOT #20	2023-08-16 13:37
MOT test number	508470287386
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #19	2022-08-18 13:39
MOT test number	993921884331
Result	✓ Passed

MOT #18	2022-08-18 13:39
MOT test number	250099577057
Result	✗ Failed
Pass with rectification	Nearside Front Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))

MOT #17	2021-08-06 15:20
MOT test number	958697318189
Result	✓ Passed

**MOT #16**

2021-01-18 12:18

**MOT test number**

456537589918

**Result**

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Lamp cluster lens broken but not showing any white light
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15**

2021-01-15 12:03

**MOT test number**

985140070006

**Result**

✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Lamp cluster lens broken but not showing any white light
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))

**MOT #14**

2020-01-16 13:29

**MOT test number**

638467787718

**Result**

✓ Passed

- Advice** Nearside Rear non obligatory fog lamp lens broken
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear exhaust heat shield insecure

**MOT #13** 2020-01-16 12:03**MOT test number** 684844486664**Result** ✗ Failed**Fail** Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Nearside Rear non obligatory fog lamp lens broken**Advice** Nearside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear exhaust heat shield insecure**MOT #12** 2019-02-04 15:17**MOT test number** 588945051285**Result** ✓ Passed**MOT #11** 2019-01-30 13:51**MOT test number** 217093575232**Result** ✗ Failed**Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Pass with rectification** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #10** 2018-01-09 11:03**MOT test number** 596147659651**Result** ✓ Passed**MOT #9** 2018-01-09 11:03**MOT test number** 591609276669**Result** ✗ Failed**Pass with rectification** Offside Rear Rear position lamp(s) not working (1.1.A.3b)

**MOT #8** 2017-01-10 12:30**MOT test number** 996051372699**Result** ✓ Passed**MOT #7** 2016-01-22 10:49**MOT test number** 655036664513**Result** ✓ Passed**MOT #6** 2016-01-22 10:49**MOT test number** 932485990513**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #5** 2015-01-26 10:27**MOT test number** 678446925072**Result** ✓ Passed**MOT #4** 2014-01-20 16:49**MOT test number** 757460824090**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-01-30 09:26**MOT test number** 887830033017**Result** ✓ Passed**Notice** Off side front tyre worn on inner edge



MOT #2	2012-02-20 13:12
MOT test number	856441752091
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.2b)

MOT #1	2011-06-30 14:48
MOT test number	605521781126
Result	✓ Passed
Notice	One of the four osr side light bulbs inop
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Notice	High level brake light inop



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
17 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	17 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-07-02
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2008-07-02	17 mi
Registration #2	2011-06-30	73.132 mi
Registration #3	2012-02-20	86.382 mi
Registration #4	2013-01-30	89.645 mi
Registration #5	2014-01-20	95.406 mi
Registration #6	2015-01-26	99.711 mi
Registration #7	2016-01-22	103.170 mi
Registration #8	2016-01-22	103.170 mi
Registration #9	2017-01-10	106.453 mi
Registration #10	2018-01-09	109.301 mi
Registration #11	2018-01-09	109.301 mi
Registration #12	2019-01-09	109.301 mi
Registration #13	2019-01-09	109.301 mi
Registration #14	2019-01-09	109.301 mi
Registration #15	2019-01-09	109.301 mi
Registration #16	2019-01-09	109.301 mi
Registration #17	2019-01-09	109.301 mi
Registration #18	2019-01-09	109.301 mi
Registration #19	2019-01-09	109.301 mi
Registration #20	2019-01-09	109.301 mi
Registration #21	2019-01-09	109.301 mi
Registration #22	2019-01-09	109.301 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

8R41849