



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Black
Year of manufacture	2008
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	164 g/km
CO2 label	G





MOT history

MOT expiry date	2025-01-09
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	33
Total items failed	12

MOT #18	2024-01-09 13:44
MOT test number	988098674645
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17	2024-01-09 13:44
MOT test number	839555234770
Result	✗ Failed
Pass with rectification	Exhaust system insecure mount loose (6.1.2 (a))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2023-01-09 13:24
MOT test number	433300957110
Result	✓ Passed
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2022-01-10 08:57**MOT test number** 220620001197**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-01-07 17:10**MOT test number** 915153129484**Result** ✓ Passed**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #13** 2020-02-20 16:48**MOT test number** 992793371231**Result** ✓ Passed**MOT #12** 2020-02-20 11:53**MOT test number** 113290182357**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Emissions not tested (8.2.1.2 (d))**MOT #11** 2018-06-06 12:41**MOT test number** 849356842485**Result** ✓ Passed**Advice** Hydraulic leak, but not excessive (8.4.1 (a) (i))



MOT #10	2017-05-08 09:23
MOT test number	693823462850
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2016-05-18 08:38
MOT test number	214349109456
Result	✓ Passed
Advice	All tyre are wearing off edges.
Advice	Nearside front shock absorber weeping oil.
Advice	Play in both front suspension rear mounting bushes.
Advice	Front brake pads are approx 70% worn.

**MOT #8** 2016-05-17 09:38**MOT test number** 878439027147**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside headlamp insecure and damaged.**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Play in both front suspension rear mounting bushes.**Fail** Nearside Headlamp aim too high and too far to the right. (1.8)**Advice** Front brake pads are aprox 70% worn.**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** All tyre are wearing off edges.**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside front shock absorber weeping oil.**MOT #7** 2015-05-18 12:22**MOT test number** 265328835154**Result** ✓ Passed**Notice** Nearside door mirror glass missing.**MOT #6** 2015-05-18 12:22**MOT test number** 996318335155**Result** ✗ Failed**Notice** Nearside door mirror glass missing.**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)

**MOT #5** 2014-05-07 14:17**MOT test number** 517617424199**Result** ✓ Passed**Notice** Nearside rear body damaged**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-05-07 10:26**MOT test number** 588637124138**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear body damaged**Fail** Offside Front Valve stem seriously misaligned (4.1.D.1e)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Valve stem seriously misaligned (4.1.D.1e)**MOT #3** 2013-05-10 08:54**MOT test number** 928550933154**Result** ✓ Passed**MOT #2** 2012-06-15 14:29**MOT test number** 268407062445**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Notice** Under-trays fitted obscuring some underside components



MOT #1	2011-06-17 11:10
MOT test number	905988161180
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DA08JZR
Plate since	2024-03-29
Current registration	 DA08JZR
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-02
Last registration	2024-01-09
Complete history	See info



Registration #1	2008-07-02	16 mi
Registration #2	2011-06-17	27.175 mi
Registration #3	2012-06-15	32.958 mi
Registration #4	2013-05-10	37.206 mi
Registration #5	2014-05-07	49.791 mi
Registration #6	2014-05-07	49.791 mi
Registration #7	2015-05-18	61.968 mi
Registration #8	2016-05-17	72.857 mi
Registration #9	2016-05-18	72.857 mi
Registration #10	2016-05-18	72.857 mi
Registration #11	2016-05-18	72.857 mi
Registration #12	2016-05-18	72.857 mi
Registration #13	2016-05-18	72.857 mi
Registration #14	2016-05-18	72.857 mi
Registration #15	2016-05-18	72.857 mi
Registration #16	2016-05-18	72.857 mi
Registration #17	2016-05-18	72.857 mi
Registration #18	2016-05-18	72.857 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1770 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BUD 428028