





## General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	Blue
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Semi Auto

# Engine & fuel consumption

Power	175 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	133 g/km
CO2 label	E







## Internet history

Entry	1

Date

Pictures

2022-05-04 33

55

Listing price

View report









source: cargurus.co.uk



# MOT history

MOT expiry date	2024-04-29
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #7	2023-04-29 10:41
MOT test number	586733244440
Result	✓ Passed
Next expiry date	2024-04-29
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement inner small bush (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement inner small bush (5.3.4 (a) (i))	

МОТ #6	2022-04-30 22:16
MOT test number	627493686766
Result	✓ Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not	resulting in excessive movement

and offside front lower (5.3.4 (a) (i))

MOT #5	2021-10-28 10:49
MOT test number	880397290314
Result	✓ Passed
Advice Emissions clean. Smoke meter unable to detect a reading.	





MOT #4		2020-10-27 11:55
MOT test numbe	er	224614846302
Result		✓ Passed
<b>Advice</b> Offsic	de Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
МОТ #3		2020-10-13 10:48
MOT test numbe	er	615509797344
Result		× Failed
DANGEROUS	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>Advice</b> Offsic	de Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	

MOT #2		2019-10-14 09:58
MOT test	number	919990443219
Result		✓ Passed
Advice	Smoke meter unable to detect a reading	
MOT #1		2018-10-30 09:54

MOT test number	672911366182
Result	✓ Passed



GK65TNO report date: 2024-03-28

Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 July 2024	Expires: 29 April 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	29 April 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETO
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CUT D
Date	*
Category	AMPT
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
*********	
**********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-09-03
Last registration	2023-04-29
Complete history	See info



Registration #1	2015-09-03	25 mi
Registration #2	2018-10-30	35.728 mi
Registration #3	2019-10-14	49.581 mi
Registration #4	2020-10-13	61.008 mi
Registration #5	2020-10-27	61.533 mi
Registration #6		11.117 est
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		11.777 esi

More info >





## Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1581 kg
Max. allowed weight	2110 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	CFGC620848