



report date: 2024-03-28

General information

Make	AUDI
Model	A1 TDI S LINE
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-27
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2025-02-25
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #14 2024-02-23 11:23**MOT test number** 929760483787**Result** Passed**Next expiry date** 2025-02-25**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear silencer outer skin corroded**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #13** 2023-02-20 11:22**MOT test number** 531964905769**Result** Passed**Advice** Rear Exhaust back box outer skin in poor condition**MOT #12** 2022-02-16 15:55**MOT test number** 857678922787**Result** Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement o/s/f lower suspension arm, rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge close to limit and worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement n/s/f lower suspension arm, rear bush (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both front, worn close to limit and wearing on edges (5.2.3 (e))

**MOT #11** 2022-02-16 14:32**MOT test number** 410862989214**Result** ✗ Failed

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure on inner sidewall (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge close to limit and worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement o/s/f lower suspension arm, rear bush (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge both front, worn close to limit and wearing on edges (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement n/s/f lower suspension arm, rear bush (5.3.4 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10 2021-02-26 12:22**MOT test number** 377159831958**Result** ✓ Passed**MOT #9** 2020-01-16 10:54**MOT test number** 274682691166**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-11-13 11:28**MOT test number** 430190452372**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2017-11-02 13:12**MOT test number** 190628721479**Result** ✓ Passed**Advice** Nearside Rear tyre out of shape**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-10-25 09:26**MOT test number** 246609178058**Result** ✓ Passed**MOT #5** 2015-11-06 16:04**MOT test number** 795159004686**Result** ✓ Passed**MOT #4** 2015-03-26 15:34**MOT test number** 336445185010**Result** ✓ Passed**MOT #3** 2015-03-26 11:41**MOT test number** 999725085053**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #2** 2014-03-26 14:03**MOT test number** 206725084082**Result** ✓ Passed**Notice** Inner tread of nearside rear tyre stepped.



MOT #1	2014-03-26 14:03
MOT test number	679755384071
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)
Notice	Inner tread of nearside rear tyre stepped.



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 February 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	25 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-04-01
Last registration	2024-02-23
Complete history	See info



Registration #1	2011-04-01	24 mi
Registration #2	2014-03-26	37.109 mi
Registration #3	2015-03-26	49.853 mi
Registration #4	2015-03-26	49.853 mi
Registration #5	2015-11-06	53.109 mi
Registration #6	2016-10-25	59.898 mi
Registration #7	2017-11-02	70.806 mi
Registration #8	2018-11-13	78.965 mi
Registration #9	2019-05-20	85.277 mi
Registration #10	2019-05-20	85.277 mi
Registration #11	2019-05-20	85.277 mi
Registration #12	2019-05-20	85.277 mi
Registration #13	2019-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi
Registration #15	2019-05-20	85.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	79%
Pedestrian	49%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1740 mm
Height	1416 mm
Length	3954 mm
Wheel base	2469 mm
Kerb weight	1140 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number

CAYA43257