





General information

Make	JAGUAR
Model	S-TYPE V8 SPORT
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	420 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	34.4 mpg
Consumption combined	24.6 mpg
CO2 emission	274 g/km
CO2 label	Μ







Internet history

Entry 2 Date

Pictures

2022-01-18

31

Listing price

View report



source: yesauto.com

Entry 1	
Date	2022-01-09
Pictures	32
Listing price	<u>View report</u>



source: cargurus.co.uk









MOT history

MOT expiry date	2024-11-25
MOT pass rate	86 %
MOT passed	19
Failed MOT tests	3
Total advice items	26
Total items failed	19

MOT #22	2023-11-02 11:51
MOT test number	103730972338
Result	✓ Passed
Next expiry date	2024-11-25

MOT #21	2023-01-26 12:37
MOT test number	367478253410
Result	🗙 Failed

Minor	Offside Rear Suspension arm ball joint dust cover severely deteriorated tracking arm (5.3.4 (b) (i))
Fail (5.3.4 (b)	Nearside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt inner (ii))
Fail ((5.3.4 (b)	Offside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt inner (ii))
Fail (5.3.4 (b)	Nearside Rear Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer (ii))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail ((5.3.4 (b)	Offside Rear Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt inner (ii))
Fail (5.3.4 (b)	Nearside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer (ii))
Fail ((5.3.4 (b)	Offside Rear Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer (ii))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail (5.3.4 (b)	Nearside Rear Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt inner (ii))
Fail ((5.3.4 (b)	Offside Rear Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer (ii))





MOT #20	2022-11-26 13:14
MOT test number	907262777681
Result	✓ Passed
Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	in excessive movement
Advice Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor Offside Rear Suspension rod ball joint dust cover severely deteriorated (5	.3.4 (b) (i))
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	excessive movement
Advice Offside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor Nearside Rear Suspension rod ball joint dust cover severely deteriorated	(5.3.4 (b) (i))

MOT #19	2022-01-10 17:01
MOT test number	707250825860
Result	✓ Passed
MOT #18	2021-03-30 12:29

MOT test number	515562202448
Result	✓ Passed



BC03FYN
report date: 2024-03-29

MOT #3	17	2021-03-25 17:49
MOT te	st number	888254332191
Result		🗙 Failed
Fail	Nearside Front Brake hose connection leaking on a hydraulic braking system (1.1.12	2 (c) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail	Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Fail (b) (ii))	Offside Rear Inner Suspension rod ball joint dust cover no longer prevents the ingres	ss of dirt (5.3.4
Fail	Offside Front Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii))
Fail	Brake performance not tested (1.2.1 (g))	
Fail	Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Fail (b) (ii))	Nearside Rear Inner Suspension rod ball joint dust cover no longer prevents the ingr	ess of dirt (5.3.4

MOT #16	2020-03-31 08:46
MOT test number	199292657389
Result	✓ Passed
MOT #15	2019-02-26 11:00

1101 #15	2019-02-20 11.00
MOT test number	648074753516
Result	✓ Passed
MOT #14	2018-03-06 13:22
MOT test number	309393906729
Result	✓ Passed

MOT #13	2017-03-18 08:25
MOT test number	971603580252
Result	✓ Passed





MOT #12	2016-03-10 11:37
MOT test number	767212177633
Result	✓ Passed
MOT #11	2015-03-20 12:38
MOT test number	518059075035
Result	✓ Passed

MOT #10	20	14-04-30 16:10
MOT test	number	417360624177
Result		Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

МОТ #9	2013-06-07 15:37
MOT test number	325268453163
Result	✓ Passed

МОТ #8	2013-05-13 13:07
MOT test number	496833933169
Result	🗙 Failed
Notice Engine covers fitted obscuring some components in the engine bay	
Fail Windscreen wiper not operating automatically when switched on (8.2.1b)	
Notice Under-trays fitted obscuring some underside components	





MOT #7		2012-05-04 09:50
MOT test	number	295775322424
Result		Passed
Notice Notice	Under-trays fitted obscuring some underside components Engine covers fitted obscuring some components in the engine bay	

MOT #6	2011-06-03 12:05
MOT test number	788854851147
Result	✓ Passed
Notice Wiper rubbers splitting.	

MOT #5		2010-06-19 09:34
MOT test	number	251500970478
Result		✓ Passed
Advice	Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Notice	Windscreen stone chipped	
Advice	Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)	

MOT #4		2009-06-19 11:02
MOT test	number	460820279170
Result		✓ Passed
Notice	All 4 tyres have cuts on outer tread	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	All 4 tyres worn on inner edge	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





МОТ #3	2008-05-23 09:25
MOT test number	714434848171
Result	✓ Passed
AdviceNearside Front brake disc slightly pitted (3.5.1h)AdviceOffside Front brake disc slightly pitted (3.5.1h)	

MOT #2	2007-07-13 09:36
MOT test number	920074997195
Result	✓ Passed
Notice Front and rear brake discs scored/// rear tyres worn on inner	edge
MOT #1	2006-07-14 09:23

	2000-07-14 09.25
MOT test number	544835296147
Result	✓ Passed



Tax & MOT check

√ Taxed	мот
Tax due: 1 March 2025	Expires: 25 November 2024
Tax status	Valid until 1 March
Days left	306
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1.E
Category	AMP
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



BCO3FYN report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-07-18
Last registration	2023-11-02
Complete history	See info



Registration #3 2007-07-13 16.60 Registration #4 2008-05-23 19.33 Registration #5 2009-06-19 26.53 Registration #6 2010-06-19 30.93 Registration #7 2011-06-03 33.44 Registration #8 2012-05-04 36.33 Registration #9 2013-05-13 38.63 Registration #10 2013-06-07 38.63 Registration #11 2014-04-30 40.63 Registration #12 2015-03-20 43.93 Registration #13 2016-03-10 47.65 Registration #14 2018-03-10 47.65 Registration #15 2016-03-10 47.65 Registration #16 2016-03-10 47.65 Registration #17 2016-03-10 47.65 Registration #18 2016-03-10 47.65 Registration #16 2016-03-10 47.65 Registration #17 2016-03-10 47.65 Registration #18 2016-03-10 47.65 Registration #17 2016-03-10 47.65 Registration #20 2016-03-10 2016			
Registration #3 2007-07-13 16.60 Registration #4 2008-05-23 19.33 Registration #5 2009-06-19 26.53 Registration #6 2010-06-19 30.93 Registration #7 2011-06-03 33.44 Registration #8 2012-05-04 36.53 Registration #9 2013-05-13 38.63 Registration #10 2013-06-07 38.63 Registration #11 2014-04-30 40.63 Registration #12 2015-03-20 43.93 Registration #13 2016-03-10 47.65 Registration #14 2018-03-10 47.65 Registration #15 2016-03-10 47.65 Registration #16 2016-03-10 47.65 Registration #17 2016-03-10 47.65 Registration #18 2016-03-10 47.65 Registration #16 2016-03-10 47.65 Registration #17 2016-03-10 47.65 Registration #18 2016-03-10 47.65 Registration #17 2016-03-10 47.65 Registration #18 2016-03-10 47.6	Registration #1	2003-07-18	22 mi
Registration #4 2008-05-23 19.5 Registration #5 2009-06-19 26.5 Registration #6 2010-06-19 30.5 Registration #7 2011-06-03 33.4 Registration #8 2012-05-04 36.5 Registration #9 2013-05-13 38.6 Registration #10 2013-06-07 38.6 Registration #11 2014-04-30 40.6 Registration #12 2015-03-20 43.5 Registration #13 2016-03-10 47.6 Registration #14 1 1 1 Registration #15 1 1 1 Registration #16 1 1 1 1 Registration #16 1 <td< th=""><th>Registration #2</th><th>2006-07-14</th><th>12.102 mi</th></td<>	Registration #2	2006-07-14	12.102 mi
Registration #5 2009-06-19 26.5 Registration #6 2010-06-19 30.9 Registration #7 2011-06-03 33.4 Registration #8 2012-05-04 36.3 Registration #8 2013-05-13 38.6 Registration #10 2013-06-07 38.6 Registration #10 2013-06-07 38.6 Registration #11 2014-04-30 40.6 Registration #12 2015-03-20 43.9 Registration #13 2016-03-10 47.6 Registration #14 1 1 1 Registration #15 1 1 1 Registration #16 1 1 1 1 Registration #17 1 <t< th=""><th>Registration #3</th><th>2007-07-13</th><th>16.618 mi</th></t<>	Registration #3	2007-07-13	16.618 mi
Registration #6 2010-06-19 30.5 Registration #7 2011-06-03 33.4 Registration #8 2012-05-04 36.5 Registration #9 2013-05-13 38.6 Registration #10 2013-06-07 38.6 Registration #11 2014-04-30 40.6 Registration #12 2015-03-20 43.9 Registration #13 2016-03-10 47.6 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1 1 Registration #17 1 1 1 1 Registration #18 1 <th>Registration #4</th> <th>2008-05-23</th> <th>19.331 mi</th>	Registration #4	2008-05-23	19.331 mi
Registration #7 2011-06-03 33.4 Registration #8 2012-05-04 36.3 Registration #9 2013-05-13 38.6 Registration #10 2013-06-07 38.6 Registration #10 2013-06-07 38.6 Registration #11 2014-04-30 40.6 Registration #12 2015-03-20 43.9 Registration #13 2016-03-10 47.6 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1 Registration #17 1 1 1 Registration #18 1 1 1 1 Registration #20 1 1 1 1 1 1 Registration #21 </th <th>Registration #5</th> <th>2009-06-19</th> <th>26.544 mi</th>	Registration #5	2009-06-19	26.544 mi
Registration #8 2012-05-04 36.3 Registration #9 2013-05-13 38.6 Registration #10 2013-06-07 38.6 Registration #11 2014-04-30 40.6 Registration #12 2015-03-20 43.9 Registration #13 2016-03-10 47.6 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1 Registration #17 1 1 1 Registration #18 1 1 1 1 Registration #20 1 1 1 1 1 1 Registration #22 1	Registration #6	2010-06-19	30.910 mi
Registration #9 2013-05-13 38.6 Registration #10 2013-06-07 38.6 Registration #11 2014-04-30 40.6 Registration #11 2015-03-20 43.9 Registration #12 2015-03-20 43.9 Registration #13 2016-03-10 47.6 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1 Registration #17 1 1 Registration #18 1 1 Registration #19 1 1 Registration #20 1 1 Registration #21 1 1 Registration #23 1 1 Registration #24 1 1	Registration #7	2011-06-03	33.401 mi
Registration #10 2013-06-07 38.8 Registration #11 2014-04-30 40.8 Registration #12 2015-03-20 43.9 Registration #13 2016-03-10 47.6 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1 Registration #17 1 1 Registration #18 1 1 Registration #19 1 1 Registration #20 1 1 Registration #21 1 1 Registration #23 1 1	Registration #8	2012-05-04	36.386 mi
Registration #112014-04-3040.8Registration #122015-03-2043.9Registration #132016-03-1047.6Registration #14	Registration #9	2013-05-13	38.837 mi
Registration #122015-03-2043.9Registration #132016-03-1047.6Registration #1447.6Registration #1547.6Registration #1647.6Registration #1747.6Registration #1847.6Registration #1947.6Registration #2047.6Registration #2147.6Registration #2347.6Registration #2447.6	Registration #10	2013-06-07	38.847 mi
Registration #132016-03-1047.6Registration #142016-03-1047.6Registration #142016-03-1047.6Registration #152016-03-1047.6Registration #152016-03-1047.6Registration #162016-03-1047.6Registration #162016-03-1047.6Registration #172016-03-1047.6Registration #182016-03-1047.6Registration #192016-03-1047.6Registration #202016-03-1047.6Registration #212016-03-1047.6Registration #222016-03-1047.6Registration #232016-03-1047.6Registration #244016-03-1047.6	Registration #11	2014-04-30	40.848 mi
Registration #14Registration #15Registration #16Registration #17Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #12	2015-03-20	43.901 mi
Registration #15Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #13	2016-03-10	47.698 mi
Registration #16Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #14		11.117 esi
Registration #17Registration #18Registration #19Registration #20Registration #21Registration #22Registration #23Registration #24	Registration #15		11.777 esi
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24	Registration #16		11.777 esi
Registration #10 Registration #20 Registration #21 Registration #22 Registration #23 Registration #24	Registration #17		11.777 esi
Registration #20 Registration #21 Registration #22 Registration #23 Registration #24	Registration #18		11.117 esi
Registration #21 Registration #22 Registration #23 Registration #24	Registration #19		11.777 esi
Registration #22 Registration #23 Registration #24	Registration #20		11.777 esi
Registration #23 Registration #24	Registration #21		11.777 esi
Registration #24	Registration #22		11.777 est
	Registration #23		11.777 mi
	Registration #24		11.777 est
Registration #25	Registration #25		10.317 est





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Max. allowed weight	2195 kg
Additional information	
Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	HB0307020431