



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | CITROEN |
| Model | C3 PURETECH FLAIR |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 104 mph |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 81 BHP |
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 109 g/km |
| CO2 label | B |





Internet history

Entry 3

| | |
|---------------|-----------------------------|
| Date | 2023-09-09 |
| Pictures | 1 |
| Listing price | View report |

□

source: [autoonline.co.uk](#)

Entry 2


| | |
|---------------|-----------------------------|
| Date | 2023-07-08 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-30 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 8 |

| | |
|------------------|------------------|
| MOT #6 | 2023-07-31 08:37 |
| MOT test number | 593198280915 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-30 |

| | |
|-----------------|---|
| MOT #5 | 2023-07-18 16:18 |
| MOT test number | 358363240705 |
| Result | ✗ Failed |
| Fail | Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| Fail | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) |
| Fail | Nearside Rear Shock absorbers has an excessively worn bush bushes worn (5.3.2 (c)) |
| Fail | Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| Fail | Nearside Front Coil spring mounting damaged and seriously weakened top mounting (5.3.1 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #4 | 2022-12-13 10:37 |
| MOT test number | 226934145424 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #3 | 2021-12-09 11:28 |
| MOT test number | 378332826716 |
| Result | ✓ Passed |

**MOT #2** 2021-12-09 09:55**MOT test number** 842649647820**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 2020-11-25 09:49**MOT test number** 920212167457**Result** ✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Exhaust mounting defective (6.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
30 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 30 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|------------|--------|
| Finance company | XXXXXXXXXX | XXXXXX |
| Date of agreement | XXXXXXXXXX | XXXXXX |
| Agreement type | XXXXXXXXXX | XXXXXX |
| Agreement term | XXXXXXXXXX | XXXXXX |
| Agreement number | XXXXXXXXXX | XXXXXX |
| Contact info | XXXXXXXXXX | XXXXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2017-12-13 |
| Last registration | 2023-07-31 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2017-12-13 | 26 mi |
| Registration #2 | 2020-11-25 | 20.294 mi |
| Registration #3 | 2020-12-20 | 20.294 mi |
| Registration #4 | 2021-12-09 | 24.237 mi |
| Registration #5 | 2021-12-09 | 24.237 mi |
| Registration #6 | 2022-05-20 | 25.277 mi |
| Registration #7 | 2022-05-20 | 25.277 mi |
| Registration #8 | 2022-05-20 | 25.277 mi |
| Registration #9 | 2022-05-20 | 25.277 mi |
| Registration #10 | 2023-07-31 | 26.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 88% |
| Children | 83% |
| Pedestrian | 59% |
| Safety systems | 58% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1829 mm |
| Height | 1474 mm |
| Length | 3996 mm |
| Wheel base | 2540 mm |
| Kerb weight | 980 kg |
| Max. allowed weight | 1550 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B2170212798 |