



HYUNDAI

WJIOXNW


report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2010
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	194 g/km
CO2 label	J



**MOT history**

MOT expiry date	2020-11-22
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	18
Total items failed	12

MOT #9 2019-11-20 12:31**MOT test number** 497703915889**Result** Passed**Next expiry date** 2020-11-22

- Advice** Under-body corrosion
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Under-tray fitted
- Advice** Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

MOT #8 2018-11-23 14:51**MOT test number** 969927984784**Result** Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #7**

2018-11-16 10:44

MOT test number

723618500534

Result**✗ Failed**

- Fail** Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #6

2017-11-20 16:43

MOT test number

831564216424

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2017-11-10 11:36**MOT test number** 407402435920**Result** ✗ Failed**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #4** 2016-06-17 13:32**MOT test number** 940163478091**Result** ✓ Passed**MOT #3** 2016-06-15 10:05**MOT test number** 448427437528**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #2** 2014-11-17 12:13**MOT test number** 936451924351**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2013-03-11 09:28
MOT test number	176110173089
Result	✓ Passed
Notice	Items removed from driver's view prior to test
Notice	Under-trays fitted obscuring some underside components
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
17 November 2020

✕
MOT

Expired:
22 November 2020

Tax status	Expired at 17 November 2020
Days left	1259 days too late
MOT expiry date	22 November 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	WJ10XNW
Plate since	2019-03-29
Current registration	WJ10XNW
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-03-09
Last registration	2019-11-20
Complete history	See info



Registration #1	2010-03-09	8 mi
Registration #2	2013-03-11	35.799 mi
Registration #3	2014-11-17	78.583 mi
Registration #4	2016-06-15	82.863 mi
Registration #5	2016-06-17	82.863 mi
Registration #6	2019-11-20	82.863 mi
Registration #7	2019-11-20	82.863 mi
Registration #8	2019-11-20	82.863 mi
Registration #9	2019-11-20	82.863 mi
Registration #10	2019-11-20	82.863 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HB9U101159