



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE (79BHP)
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.400 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	152 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-06-18
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	32
Total items failed	9

MOT #18	2024-01-12 11:47
MOT test number	331854002552
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT #17	2024-01-04 11:45
MOT test number	173029701835
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm outer edge (5.2.3 (e))
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Fail	Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Tyre tread depth below requirements of 1.6mm Nearside and offside front inner edges (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))
Fail	Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #16** 2023-01-05 15:12**MOT test number** 359489453187**Result** ✓ Passed**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Parking brake lever defective but can be satisfactorily operated Serviceable travel at the lever (1.1.6 (d))**MOT #15** 2022-01-05 11:33**MOT test number** 677219942353**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Parking brake lever defective but can be satisfactorily operated serviceable travel at the lever (1.1.6 (d))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #14** 2020-12-28 11:29**MOT test number** 359517028558**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2019-12-18 10:22**MOT test number** 738639111056**Result** ✓ Passed**Advice** Central Rear Seat belt buckle slightly damaged (7.1.2 (d))

**MOT #12**

2018-12-14 10:14

MOT test number

192600679240

Result

✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

(a) (i)) Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11

2018-01-02 12:13

MOT test number

581791898882

Result

✓ Passed

Advice

Child seat fitted.

Advice

Both front tyres wearing on inner tread. 185/60/r14-82h

MOT #10

2016-12-29 09:55

MOT test number

779316566361

Result

✓ Passed

MOT #9

2015-12-07 11:25

MOT test number

393383343481

Result

✓ Passed

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice

Engine covers

Advice

Child seats

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice

Under trays

**MOT #8** 2014-12-16 15:58**MOT test number** 776090654334**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7** 2014-12-16 09:37**MOT test number** 169220854313**Result** ✗ Failed**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp insecure (1.7.3)**MOT #6** 2013-12-23 11:57**MOT test number** 627137753306**Result** ✓ Passed**MOT #5** 2012-12-19 10:09**MOT test number** 968364552347**Result** ✓ Passed

**MOT #4** 2012-01-06 11:24**MOT test number** 589856502086**Result** ✓ Passed**MOT #3** 2010-12-22 12:11**MOT test number** 332006950307**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2010-12-22 09:47**MOT test number** 460756950457**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Nsf tyre worn very low**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2010-01-04 10:28**MOT test number** 281334800009**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-01-05
Last registration	2024-01-12
Complete history	See info



Registration #1	2007-01-05	17 mi
Registration #2	2010-01-04	19.083 mi
Registration #3	2010-12-22	22.581 mi
Registration #4	2010-12-22	22.581 mi
Registration #5	2012-01-06	27.790 mi
Registration #6	2012-12-19	31.132 mi
Registration #7	2013-12-23	33.259 mi
Registration #8	2014-12-16	37.570 mi
Registration #9	2014-12-16	37.570 mi
Registration #10	2015-12-07	43.601 mi
Registration #11	2016-12-07	49.632 mi
Registration #12	2017-12-07	55.663 mi
Registration #13	2018-12-07	61.694 mi
Registration #14	2019-12-07	67.725 mi
Registration #15	2020-12-07	73.756 mi
Registration #16	2021-12-07	79.787 mi
Registration #17	2022-12-07	85.818 mi
Registration #18	2023-12-07	91.849 mi
Registration #19	2024-01-12	97.880 mi
Registration #20	2024-01-12	97.880 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles

2

Engine number

BUD361776