



RENAULT

CYIOEEZ

report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO SL19 DCI 70
Colour	Grey
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-17
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	42
Total items failed	1

MOT #17	2023-10-20 12:27
MOT test number	511252626804
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
Advice	Front Macpherson strut corroded but not seriously weakened Both (5.3.3 (b) (i))
Advice	Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #16**

2023-10-06 08:14

MOT test number

468635712888

Result**✗ Failed**

MAJOR Nearside Headlamp has a product on the lens so that the light output is severely reduced Clouded (4.1.4 (b))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Macpherson strut corroded but not seriously weakened Both (5.3.3 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

MAJOR Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Headlamp aim too high (4.1.2 (a))

Advice Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

MAJOR Emissions unable to be completed (8.2.2.2 (e))

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Stop lamp(s) not working High level (4.3.1 (a) (ii))

MOT #15

2022-10-26 15:46

MOT test number

897851004385

Result**✓ Passed**

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #14**

2022-10-21 10:24

MOT test number

876412722968

Result**✗ Failed**

- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- MAJOR** Registration plate lamp missing in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Offside Headlamp aim too high (4.1.2 (a))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #13

2021-10-25 16:15

MOT test number

902975714033

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2021-10-13 08:03

MOT test number

917699041121

Result**✗ Failed**

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Offside Rear Brake pipe excessively corroded to nearside (1.1.11 (c))

MAJOR Offside Rear Brake pipe excessively corroded to front x2 (1.1.11 (c))

MAJOR Nearside Parking brake inoperative on one side (1.4.1 (a))

MOT #11

2020-10-14 08:58

MOT test number

725785962872

Result**✓ Passed**

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #10

2019-10-08 15:03

MOT test number

820072970854

Result**✓ Passed**

**MOT #9** 2019-10-02 15:04**MOT test number** 985337380396**Result** ✗ Failed**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #8** 2018-09-18 15:11**MOT test number** 170908601352**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #7** 2018-09-18 15:11**MOT test number** 568538812532**Result** ✗ Failed**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #6** 2017-09-09 09:52**MOT test number** 746031429295**Result** ✓ Passed**MOT #5** 2016-09-30 10:34**MOT test number** 526421208134**Result** ✓ Passed



MOT #4	2015-09-16 12:12
MOT test number	216308826318
Result	✓ Passed
MOT #3	2015-03-31 09:18
MOT test number	278200695069
Result	✓ Passed
MOT #2	2014-04-02 08:46
MOT test number	555682294082
Result	✓ Passed
MOT #1	2013-04-05 09:14
MOT test number	296055493089
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 October 2024

Tax status		Valid until 1 February
Days left		277
MOT expiry date		25 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-21
Last registration	2023-10-20
Complete history	See info



Registration #1	2010-04-21	26 mi
Registration #2	2013-04-05	29.433 mi
Registration #3	2014-04-02	39.169 mi
Registration #4	2015-03-31	48.597 mi
Registration #5	2015-09-16	51.516 mi
Registration #6	2016-09-30	74.957 mi
Registration #7	2017-09-09	86.901 mi
Registration #8	2018-09-18	100.911 mi
Registration #9	2018-09-18	100.911 mi
Registration #10	2019-10-02	117.348 mi
Registration #11	2019-10-02	117.348 mi
Registration #12	2019-10-02	117.348 mi
Registration #13	2019-10-02	117.348 mi
Registration #14	2019-10-02	117.348 mi
Registration #15	2019-10-02	117.348 mi
Registration #16	2019-10-02	117.348 mi
Registration #17	2019-10-02	117.348 mi
Registration #18	2019-10-02	117.348 mi
Registration #19	2019-10-02	117.348 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	2133 mm
Height	1844 mm
Length	4213 mm

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D082219