



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S AC ECOFLEX
Colour	Blue
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-11
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	22
Total items failed	5

MOT #11	2023-09-23 09:20
MOT test number	529253370642
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10	2022-09-29 14:03
MOT test number	332186711284
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))
Advice	Brake pipe corroded, covered in grease or other material front to rear brake pipes corroded (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

**MOT #9** 2022-09-29 14:03**MOT test number** 631815612531**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Brake pipe corroded, covered in grease or other material front to rear brake pipes corroded (1.1.11 (c))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #8** 2021-10-11 08:09**MOT test number** 381201657753**Result** ✓ Passed**MOT #7** 2021-01-04 15:02**MOT test number** 491291859785**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2021-01-04 12:10**MOT test number** 810704952132**Result** ✗ Failed**Fail** Nearside Windscreen washer not working (3.5 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Windscreen washer not working (3.5 (a))

**MOT #5** 2020-01-03 10:05**MOT test number** 132645719439**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2019-02-14 09:42**MOT test number** 629778992975**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2018-02-20 12:49**MOT test number** 529976137450**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit worn to 3mm, worn on outer edge & developing slight cracks in tread (4.1.E.1)**Advice** Nearside Front Outer Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Both Rear Tyres Developing Slight Cracks In Tread**MOT #2** 2017-02-10 12:51**MOT test number** 776098028928**Result** ✓ Passed**Advice** Front both side lights slight blue**Advice** Offside Front tyre close to the limit 185/60/15**Advice** Rear centre head rest missing**Advice** Nearside Front tyre cracked and close to the limit 185/60/15



MOT #1	2015-12-21 13:47
MOT test number	375338065183
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-21
Last registration	2023-09-23
Complete history	See info



Registration #1	2012-12-21	18 mi
Registration #2	2015-12-21	14.203 mi
Registration #3	2017-02-10	16.780 mi
Registration #4	2018-02-20	18.439 mi
Registration #5	2019-02-14	20.188 mi
Registration #6	2020-01-03	28.058 mi
Registration #7	2021-01-04	35.807 mi
Registration #8	2022-05-20	35.277 mi
Registration #9	2022-05-20	35.277 mi
Registration #10	2022-05-20	35.277 mi
Registration #11	2022-05-20	35.277 mi
Registration #12	2022-05-20	35.277 mi
Registration #13	2023-09-23	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	985 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1112936