



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg







LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-30
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT #22	2022-09-06 15:00
MOT test number	353819128785
Result	✓ Passed
Next expiry date	2023-09-23
<b>Advice</b>	Offside Front Upper Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Nail in tyre
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #21	2022-09-06 15:00
MOT test number	927462232634
Result	✗ Failed
<b>Advice</b>	Offside Front Upper Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Nail in tyre
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Pass with rectification</b>	Offside Front Headlamp aim too high (4.1.2 (a))

MOT #20	2021-09-24 08:59
MOT test number	171852631053
Result	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2020-09-19 17:12
MOT test number	954063556605
Result	✓ Passed

**MOT #18** 2019-09-17 11:27**MOT test number** 859361420545**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17** 2018-09-04 12:08**MOT test number** 281523309418**Result** ✓ Passed**MOT #16** 2018-09-04 08:28**MOT test number** 139944102793**Result** ✗ Failed**Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15** 2017-09-12 08:02**MOT test number** 726285262044**Result** ✓ Passed**MOT #14** 2016-09-01 11:43**MOT test number** 996207564451**Result** ✓ Passed**MOT #13** 2015-08-26 00:00**MOT test number** 257533827284**Result** ✓ Passed**Advice** Offside Front Radius arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Fuel tank strap corroded

**MOT #12**

2015-08-22 09:38

**MOT test number**

656281586276

**Result**

✗ Failed

**Advice**

Offside Front Radius arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Fuel tank strap corroded

**Fail**

Exhaust has a major leak of exhaust gases (7.1.2)

**Fail**

Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #11**

2014-09-22 14:33

**MOT test number**

45525364256

**Result**

✓ Passed

**Notice**

Fuel tank strap corroded.

**Advice**

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #10**

2013-09-20 15:33

**MOT test number**

278373163255

**Result**

✓ Passed

**MOT #9**

2012-09-17 11:44

**MOT test number**

359461162232

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Front Brake pad(s) wearing thin (3.5.1g)

**Notice**

Nail in offside rear tyre

**Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2011-09-21 12:45**MOT test number** 195624461231**Result** ✓ Passed**Notice** O/S/F lower arm rear bush starting to pull out**Notice** Slight movement in O/S/F steering arm**MOT #7** 2010-08-23 14:36**MOT test number** 452225030258**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2009-08-26 12:36**MOT test number** 884168239245**Result** ✓ Passed**Notice** O/S/F lower arm rear bush starting to pull out.**Notice** Cut to N/S/F tyre side wall but not down to cords.**Notice** Slight perishing to both rear tyre side walls.**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2008-08-28 16:41**MOT test number** 322091548248**Result** ✓ Passed**Notice** Both rear tyres slightly perished.**Notice** Slight movement in N/S/F lower ball joint.**Notice** Small cut to N/S/F tyre side wall.

**MOT #4** 2008-08-28 11:43**MOT test number** 204871548292**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Notice** Both rear tyres slightly perished.**Fail** Rear Exhaust has part of the system excessively deteriorated (7.1.1a)**Notice** Slight movement in N/S/F lower ball joint.**Notice** Small cut to N/S/F tyre side wall.**MOT #3** 2007-08-28 09:57**MOT test number** 512550947248**Result** ✓ Passed**MOT #2** 2007-08-24 10:26**MOT test number** 503596137261**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Emissions not tested (7.0)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**MOT #1** 2006-08-24 11:05**MOT test number** 752156936293**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-05-24
Last registration	2022-09-06
Complete history	<a href="#">See info</a>



Registration #1	2002-05-24	12 mi
Registration #2	2006-08-24	13.943 mi
Registration #3	2007-08-24	20.755 mi
Registration #4	2007-08-28	20.755 mi
Registration #5	2008-08-28	26.673 mi
Registration #6	2008-08-28	26.673 mi
Registration #7	2009-08-26	32.618 mi
Registration #8	2010-08-23	36.871 mi
Registration #9	2011-09-21	38.534 mi
Registration #10	2012-09-17	40.055 mi
Registration #11	2013-09-20	41.367 mi
Registration #12	2014-09-22	42.678 mi
Registration #13	2015-09-22	42.678 mi
Registration #14	2016-09-22	42.678 mi
Registration #15	2017-09-22	42.678 mi
Registration #16	2018-09-22	42.678 mi
Registration #17	2019-09-22	42.678 mi
Registration #18	2020-09-22	42.678 mi
Registration #19	2021-09-22	42.678 mi
Registration #20	2022-09-06	42.678 mi
Registration #21	2023-09-22	42.678 mi
Registration #22	2024-03-29	42.678 mi
Registration #23	2024-03-29	42.678 mi
Registration #24	2024-03-29	42.678 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSB93834447