



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	PROACE L1H1 HDI 1200 P/V
Colour	White
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





## Internet history

### Entry 1

Date 2021-12-24

Pictures 54

Listing price [View report](#)



source: yesauto.com



MOT history

MOT expiry date	2024-10-09
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	15

MOT #11	2023-10-10 07:05
MOT test number	629955999281
Result	✓ Passed
Next expiry date	2024-10-09
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #10**

2023-10-06 14:31

**MOT test number**

773202041297

**Result**

✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Front Tyre has ply or cords exposed cut/cord 215/60/16 (5.2.3 (d) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #9**

2022-10-08 13:36

**MOT test number**

786276565963

**Result**

✓ Passed

**MOT #8**

2022-10-05 16:32

**MOT test number**

639396121507

**Result**

✗ Failed

- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn has excessive play (5.3.4 (a) (i))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Front Oil leaking excessively from engine (8.4.1 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #7**

2022-10-05 15:33

**MOT test number**

375836776972

**Result**

✗ Failed

**Advice**

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail**

Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail**

Nearside Front Suspension arm ball joint excessively worn has excessive play (5.3.4 (a) (i))

**Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail**

Front Oil leaking excessively from engine (8.4.1 (a) (i))

**Fail**

Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Minor**

Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail**

Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #6**

2021-08-25 14:09

**MOT test number**

710347444482

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #5**

2020-08-20 15:21

**MOT test number**

255146674961

**Result**

✓ Passed

**Advice**

Offside Front daytime running light inop

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #4**

2019-08-23 13:31

**MOT test number**

962955504384

**Result**

✓ Passed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #3** 2018-08-21 13:39**MOT test number** 194064748252**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2017-08-29 16:38**MOT test number** 855018304721**Result** ✓ Passed**MOT #1** 2017-08-29 16:38**MOT test number** 182347195200**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam replaced headlight bulb (1.7.5a)



Tax & MOT check

X

Untaxed

Tax expired:  
15 March 2024

✓

MOT

Expires:  
9 October 2024

Tax status	Expired at 15 March 2024
Days left	45 days too late
MOT expiry date	9 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-08-15
Last registration	2023-10-10
Complete history	<a href="#">See info</a>



Registration #1	2014-08-15	19 mi
Registration #2	2017-08-29	41.247 mi
Registration #3	2017-08-29	41.247 mi
Registration #4	2018-08-21	53.122 mi
Registration #5	2019-08-23	63.829 mi
Registration #6	2020-08-20	71.143 mi
Registration #7	2021-08-25	77.385 mi
Registration #8	2022-08-20	85.277 mi
Registration #9	2022-08-20	85.277 mi
Registration #10	2022-08-20	85.277 mi
Registration #11	2022-08-20	85.277 mi
Registration #12	2022-08-20	85.277 mi
Registration #13	2023-10-10	85.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1986 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1798 kg
Max. allowed weight	2898 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	RH04063599