




report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S
Colour	Red
Year of manufacture	2011
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2025-02-08
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	29
Total items failed	4

MOT #17	2024-02-03 09:59
MOT test number	552553318289
Result	✓ Passed
Next expiry date	2025-02-08
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Brake pedal wearing smooth (1.1.2 (c))

MOT #16	2024-02-03 09:59
MOT test number	965554699714
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Brake pedal wearing smooth (1.1.2 (c))

**MOT #15** 2023-02-09 17:48**MOT test number** 614255412039**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear All direction indicators slightly discoloured both sides (4.4.3 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14 2023-02-09 17:48**MOT test number** 714702152568**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear All direction indicators slightly discoloured both sides (4.4.3 (a))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13 2022-01-08 16:30**MOT test number** 513527519916**Result** ✓ Passed**MOT #12** 2022-01-05 12:23**MOT test number** 633163980472**Result** ✗ Failed

- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))

**MOT #11** 2020-11-16 17:04**MOT test number** 660210346301**Result** ✓ Passed**MOT #10** 2020-11-16 10:54**MOT test number** 564840844056**Result** ✗ Failed**MAJOR** Nearside Rear Brake pipe excessively corroded chassis (1.1.11 (c))**MOT #9** 2019-11-18 11:15**MOT test number** 640875095756**Result** ✓ Passed**Advice** Nearside Rear Axle deformed but serviceable (5.1.1 (a))**MOT #8** 2018-12-13 13:03**MOT test number** 909871729587**Result** ✓ Passed**MOT #7** 2018-12-12 12:30**MOT test number** 963388859807**Result** ✗ Failed**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #6** 2018-01-22 10:00**MOT test number** 542703230862**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2017-01-18 12:03**MOT test number** 140787339824**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-01-19 16:13**MOT test number** 330787206266**Result** ✓ Passed**MOT #3** 2016-01-19 16:13**MOT test number** 528375383655**Result** ✗ Failed**Pass with rectification** Offside Front coil spring broken (2.4.C.1a)**MOT #2** 2015-01-12 17:43**MOT test number** 338042015026**Result** ✓ Passed**MOT #1** 2013-12-30 12:12**MOT test number** 236984763301**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BV60OCM
Plate since	2019-06-29
Current registration	 BV60OCM
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-01-21
Last registration	2024-02-03
Complete history	See info



Registration #1	2011-01-21	28 mi
Registration #2	2013-12-30	11.297 mi
Registration #3	2015-01-12	15.323 mi
Registration #4	2016-01-19	34.734 mi
Registration #5	2016-01-19	34.734 mi
Registration #6	2017-01-18	56.614 mi
Registration #7	2018-01-22	78.247 mi
Registration #8	2018-12-12	86.519 mi
Registration #9	2018-12-13	86.519 mi
Registration #10	2019-01-22	86.519 mi
Registration #11	2019-01-22	86.519 mi
Registration #12	2019-01-22	86.519 mi
Registration #13	2019-01-22	86.519 mi
Registration #14	2019-01-22	86.519 mi
Registration #15	2019-01-22	86.519 mi
Registration #16	2019-01-22	86.519 mi
Registration #17	2019-01-22	86.519 mi
Registration #18	2019-01-22	86.519 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1320032